DISTRIBUTION		P. O. BOX 208 BECEIVED				Form C-103 Revised 10-1-1	
SANTA FE	SANTA	FE, NEW MEX	FCO 87501				
FILE				50	. Indicate Type of L	_e15•	
U.1.C.1.		ככו	2 0 1982	ļ	State X	Fee -	
LAND OFFICE		251	2 U IJOE	<u> </u>			
DPERATOR				3.	State Oil & Gas Le	230 140.	
		-). C. D.		LG - 7559	•	
SUI	NDRY NOTICES AND REF	PORTS ON WELL	SIA, OFFICE				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)						7111.111.	
1.	OTHER. DRY HOLE			7.	, Unit Agreement No	me .	
WELL WELL	OTHER. DET HOLE		· · · · · · · · · · · · · · · · · · ·		Form or Lease 1-an		
2. Name of Operator							
SANDERS PETROLEUM CORPORATION					KoKo State		
3. Address of Operator					Well No.		
11000-D Spain Rd.	N.E., Albuquerque,	New Mexico 8	7111		#1		
4. Location of Well				10	0. Field and Pool, o	r Wilacat	
P	896 PEET FROM THE	South	717	,	Wildcat 🎉 🐍	15 A	
	PEET FROM THE	LINE	AND	LEET PROM	misanni	mm	
T = = b	10	110	105				
THELINE, S	ECTION 10 TOWNS	115	ANGE	— нмрм. 🚫			
						////////	
	15. Elevation (Show whether DF, RT	, GR, etc.)	113	2. County		
	5072	2 GL		L	incoln	7777777	
16. Cha	ck Appropriate Box To	Indicate Nature	of Notice Repo	or Other	Data		
	• • •	Indicate Nature			EPORT OF:		
NOTICE O	F INTENTION TO:		2083	EQUENT R	EPURIUF:		
		دعا				_	
PERFORM REMEDIAL WORK	PLUS AND	ABANDON REMED	IAL WORK		ALTERING C	ASING	
TEMPORARILY ABANDON		COMMI	ENCE DRILLING OPHS.		PLUG AND A	SANDONMENT A	
PULL OR ALTER CASING	_ CHANGE PL	ANS CASING	TEST AND CEMENT JQ	• 📋			
-		07.	1ER				
GTHER							
17. Describe Proposed or Complete	ed Operations (Clearly state all	persinent desails, and	l give pertinent dates	, including est	imated date of start.	ing any propose	
work) SEE RULE 1103. Set	following plugs du	ring completio	on attempt of	Abo sands	:		
	CIBP @ 2920' w/ cer	ment to 2895 '.			•		
	CIBP @ 2840' w/ cer	ment to 2805'.	•				
Set following plu	igs for final pluggi	ng. P & A con	npleted 9-12-8	2. The 4	½" casing was	s	
out at 1200', rec	covered 1200' casing	. Swabbed dry	, no fluid en	try from	open hole in	terval	
1000' - 1200'.		·					
· .	PLUG # SACKS	CEMENT	FROM	ТО			
<u>.</u>	$\frac{1}{1}$ $\frac{3HSRB}{1}$		2440	2540			
	2 2		1130	1250			
	3 3		1000	1050			
	4 1		1000	no fill			
	5 3		990	1000	••		
	6 1		874		td 1200# bef	ore perf	
			783	no fill	.cuzoo# Der	Yeso)	
	7 2					1630)	
		5	783 703	no f ill			
		5	703	783			
		5	703	no fill			
•		0	335	703			
	•	5	225	335			
	13	0	0	60			
		100000 00+ 00-	nnleted D s	Δ Q_12_82)		
Installed regular	tion pipe marker. C	Teaunh Hor Col	npreced. I a	11 7-12-02	- •		
18. I hereby certify that the inform	ation above is true and complet	e in the near of mis au					
Male Asi dera President					Contomb	er 16, 198	
araily /	for dere	Preside	enc	-	DATE Septemb	CI 10, 130	
	V					-	
			•				