

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT Artesia, NM 88210

DRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. **O. C. D.**
OIL WELLS ☒ ARTESIA, OFFICE ☐ P&A

2. NAME OF OPERATOR
Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1830 FNL & 1980 FWL, Sec. 27-T6S-R19E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5003' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM 37080

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Macho Uno ABL Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Wildcat - *Also*

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit F, Sec. 27-6S-19E

12. COUNTY OR PARISH
Lincoln

13. STATE
NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal permission obtained 2-3-85 from Armando Lopez, BLM, Roswell, to plug and abandon well as follows:

Plug #1: w/30 sx Class "C" at 2153-2253'.
Plug #2: w/30 sx Class "C" at 993-1094'
Plug #3: w/10 sx Class "C" at 100' to surface.

Set dry hole marker. Clean and restore location.

18. I hereby certify that the foregoing is true and correct

SIGNED *Luanna Goodlett* TITLE Production Supervisor DATE 2-5-85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED
PETER W. CHESTER

FEB 26 1985

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWEEL RESOURCE AREA