

**RECEIVED BY**  
**MAR 12 1985**  
**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ O. C. D.  
☐ OIL WELL ☐ GAS WELL ☐ OTHER P&A

2. NAME OF OPERATOR  
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1960 FSL & 1980 FEL, Sec. 19-T2S-R17E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
5414' GR

5. LEASE DESIGNATION AND SERIAL NO.  
NM 37410

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Cowboy Mesa AAY Federal

9. WELL NO.  
1-Y

10. FIELD AND POOL, OR WILDCAT  
Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit J, Sec. 19-T2S-R17E

12. COUNTY OR PARISH  
Lincoln

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Verbal permission obtained from Peter Chester, BLM, Roswell, by Tim Bussell, on 2-11-85 to plug and abandon well as follows:

- Plug #1: Set 50 sx plug 1440-1340'
- Plug #2: Set 40 sx plug 550-450'
- Plug #3: Set 10 sx plug at surface




18. I hereby certify that the foregoing is true and correct

SIGNED Peter Chester TITLE Production Supervisor DATE 2-12-85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:



\*See Instructions on Reverse Side