	7.5						
NO. OF COPIES RECEIVED	_ 3_					Form C-103	
DISTRIBUTION						Supersedes C-102 and (
SANTA FE			NEW MEXICO OIL CO	NSERVATION (COMMISSION	Effective 1	
FILE	1	سا		_		_	
U.S.G.S.				R	ECEIVE	5a. Indicate Ty	pe of Lease
LAND OFFICE						State 🛣	Fee
OPERATOR	1				APR 5 1973	5. State Oil & (
						L-(6592
(DO NOT USE THIS	SUL	NDRY NOTIC	CES AND REPORTS C	N WELLS			
	SE "APPL	LICATION FOR PE	DRILL OR TO DEEPEN OR PLU RMIT - " (FORM C-101) FOR	G BACK TO A DIFFE SUCH PROPOSALS.)	RENTI RESERVOIR.	<u> </u>	
	A5 🖳		Dan 11-1 -		Maria Banasa (1900) a a a companio	7. Unit Agreem	ent Name
	ELL L	OTHER	Dry Hole				
2. Name of Operator Weldon S. Guest	T 2 4	t Wale				8. Farm or Lea	
3. Address of Operator	<u> </u>	. J. WOIL	80R			Dia	18
•	a A G	es Service	es, Inc., Box 76	3 Hobbe N	Jan Marica 882	9. Well No.	
4. Location of Well		#0 DOLVICO	es, mer, box 70	J, 110000, 1	IEM MENTO 005		Pool, or Wildcat
P		1980	Mort	h	1000		dcat
UNIT LETTER	 , .	1700	FEET FROM THE NOTE	LINE AND	1700 FEET FRO	M	
Uaab		1,	4 99		11		
THE West	_ LINE, S	SECTION	6 TOWNSHIP	NANGE _	NMPI	~ <i>(</i>	
mmmm	m	errerrerr	15 [2]	DE DE CD			<i>1111111111</i>
		UIIIII.	15. Elevation (Show wheth	ier Dr., KI, GK, e	etc.)	12. County	
	71111	71111111					
10.	Che	ck Appropri	iate Box To Indicate	Nature of No	otice, Report or O	ther Data	
NOT	TICE O	F INTENTIO	ON TO:	1	SUBSEQUEN	IT REPORT OF	₹:
				_			
PERFORM REMEDIAL WORK			PLUG AND ABANDON	REMEDIAL WO	PRK	ALTE	ERING CASING
TEMPORARILY ABANDON				COMMENCE DE	RILLING OPNS.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS	CASING TEST	AND CEMENT JOB		
			_	OTHER			[
OTHER				7			
17. Describe Proposed or (work) SEE RULE 1103	Complete 3.	ed Operations (Clearly state all pertinent o	letails, and give p	pertinent dates, includin	g estimated date o	f starting any proposed
, ,							
•	Sut	bject well	l plugged for abo	andonment a	s follows:		
					_		
•			sack plug @ total	l depth 791	.5		
			sack plug @ 7300				
		4 0 <i>t</i>	sack plug 4700 -	4800			
		40 1	sack plug 2600 -	2700			
		40 1	sack plug 1960 -	2060			
			sacks @ surface t		tion marker		
			between all plus	-			
			gging complete 3				
				, = : • : :			
	Loc	cation to	be cleared, leve	alled and m	ade ready for		
			on as soon as pi				
	, ,						
Csg. lepton	rholi	137-20					
,		878-26	3/7				
		13%-20	554				
		•					
18. I hereby certify that the	e informa	ation above is t	rue and complete to the bes	st of my knowledg	e and belief.		
. //	. 1	1 21					
HUAMANA	, <i>!!</i> -	Shop		Agent			6/4/73
SIGNED WOOD	1/0		TITLE			DATE	
SIGNED Monna	-						
ADDROVED OF SOLL	<u> </u>	est o	. TITLE	VIL AND GAS IA	18 <i>PECTOR</i>	በ ር ፕ	2 1 1974
APPROVED BY		Heave	TITLE			_ DATE OUT	<u> </u>