

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 'LOCATE'
(Other instru is on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N M 8811

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal (USA) 'E'

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T-18-S, R-8-E

12. COUNTY OR PARISH

Otero

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR TEXACO Inc.	3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well located 660' from the South Line and 660' from the West Line of Section 10, T-18-S, R-8-E, Unit Letter M, Otero County, New Mexico.	14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3998.6 (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TEXACO proposes to plug and abandon subject well as follows:

1. Set cement plugs from:

- 7465' to TD 7785' w/120 sx Class C cement
- 7210' to 7310' w/40 sx Class C cement
- 7000' to 7100' w/40 sx Class C cement
- 6550' to 6650' w/40 sx Class C cement
- 5982' to 6082' w/60 sx Class C cement.

2. Set 10 sx cement plug at surface.

3. Install 4" marker extending 4' above ground level and clean location.

Note: Verbal approval to plug and abandon by USGS - Mr. R. L. Beckman at 1:30 PM, February 27, 1970.
Verbal approval to plug and abandon by NMOCC - Mr. W. A. Gressett at 1:40 PM, February 27, 1970.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

Assistant District

TITLE Superintendent

DATE March 2, 1970

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

MAR 4 1970

*See Instructions on Reverse Side

O. C. C.
ARTESIA, OFFICERECEIVED
MAR 3 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED

R. L. BECKMAN

ACTING DISTRICT SUPERINTENDENT