NO. OF COPIES RECEIVED 3			Form C-103
DISTRIBUTION		ም ህም ረጥ ምን 13 - 4 የም ርሜ	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONS	SERVATION COMMISSION	Effective 1-1-65
FILE	_		
U.S.G.S.	\dashv	OCT 1 6 1980	5a. Indicate Type of Lease
OPERATOR I	-		State X Fee 5. State Oil & Gas Lease No.
OFERATOR	_	O. C. D.	1
SUNDRY NOTICES AND REPORTS ON WELLS			MAN
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			
1. OIL GAS	DDV		7. Unit Agreement Name
WELL WELL	OTHER- DRY		
2. Name of Operator			8. Form or Lease Name
PENNZOIL COMPANY 3. Address of Operator	-		Southland 32 State
P.O. Drawer 1828, Midland, Texas 79702			1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER P	660 FEET FROM THE South	LINE AND FEET FROM	Wildcat
THE East LINE, SEC	32 TOWNSHIP 25-S	18-E	
mmmmm			
	15. Elevation (Show whether 3993.6 GR	DF, RT, GR, etc.)	12. County Otero
16.			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF	INTENTION TO:	SUBSEQUENT	FREPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER Attempted Comp	letion X
OTHER			
17. Describe Proposed or Completed	Operations (Clearly state all pertinent det	tails, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.		, , , , , , , , , , , , , , , , , , , ,	and the second and th
9/5/80 - 9/23/80 W.O. completion unit. 9/24/80 RU completion & ran velocity survey. Perf 4 holes at 3310'.			
9/25/80 Set retainer at 3207' and cmt w/350 sx Cl C Thixomix.			
9/26/80 Ran temp survey, found TOC at 2210'.			
9/27/80- 9/29/80 Drilled out retainer & cmt.			
9/30/80 Ran bond log. Had good cmt from 3400-2200'. Set 4-1/2" CIBP @ 3375'. Perf at 3286,			
90,91,96,98 (total 5 holes).			
10/01/80 Treated zone 3286-98' w/500 gals 15% acid. Swbd back all load. No Shows.			
10/02/80 Continued swbg. No shows.			
10/03/80 Set 4-1/2" CIBP @ 3250'. Perf at 3127,29,31,35,38,40,42,83,84,86,89 (total 11 holes).			
Treated w/1000 gals 15% acid. Swbd back all load. No shows.			
	wbg. No shows.		
10/05/80 Shut down f	or Sunday.		
10/06/80 Set 4-1/2"	CIBP @ 3110'. Perf at 308	0,81,82,83,84,85,86 (tot	al 7 Holes).
10/07/80 Treated zon	10/07/80 Treated zone 3080-86' w/500 gals 15% acid. Swbd back all load. No shows.		
10/08/80 Continued s	wba. No shows.		
10/09/80 Dump 35 ft cmt on top of CIBP @ 3110'. Set another CIBP @ 3000' & dump 35' cmt on			
top. Perf @ 2901,03,05,29,38,42,53,55,60,62 (total 10 holes). Starting swbg. No shows			
10/10/80 Treated zon	e 2901-62 w/750 gals 15%	acid. Swbd back all load	. No shows. Prep to P&A.
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
O O O O O O O O O O O O O O O O O O O			
(17/1)	Les Com	Operations Engineer	10/15/80
SIGNED TITLE DATE			
, , /			-
APPROVED BY WY	presset TITLE_	SUPERVISOR, DISTRICT H	DATE OCT 2 1 1980

CONDITIONS OF APPROVAL, IF ANY: