

C15F

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Harvey E. Yates Company

3. Address and Telephone No.  
P.O. Box 1933 Roswell, New Mexico 88202

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
990' FNL & 1980' FEL, Sec. 14, T26S, R21E

5. Lease Designation and Serial No.  
NM-71526

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation  
19008

Bennett Ranch Unit

8. Well Name and No.

Bennett Ranch Unit #1

9. API Well No.

30-035-20027

10. Field and Pool, or Exploratory Area

Wildcat

11. County or Parish, State

Otero, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well drilled to TD at 2643'. Lost hole and unable to continue due to parted 7" casing run to 2450' and parted at 2280'. Will P&A and drill replacement well. Spot 100' cement plug from 2330' to 2230' and tag. Perforate 7" casing at 950' and spot 100' cement plug from 950' to 850' in and out of 7" across 8 5/8" casing shoe and tag. Cut off wellhead. Install dry hole marker. Will commence replacement well when equipment is available.

Called BLM 24 hrs prior to commencement. Obtained verbal approval of procedure from Armando Lopez 6/18/97.

14. I hereby certify that the foregoing is true and correct

Signed Steven M. Yates Steven M. Yates

Title V. P.

Date 6/19/97

(This space for Federal or State office use)

(ORIG. SGD.) ARMANDO A. LOPEZ

Approved by \_\_\_\_\_

Conditions of approval, if any:

Title

**PETROLEUM ENGINEER**

Date

6/19/97