

UNITED STATES **Artesia, NM 88210**
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS


(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Getty Oil Company ✓
3. ADDRESS OF OPERATOR
P.O. Box 730, Hobbs, N.M. 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Unit Ltr. B, 2310' FEL, 990' FNL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐		☐
FRACTURE TREAT	☐		☐
SHOOT OR ACIDIZE	☐		☐
REPAIR WELL	☐		☐
PULL OR ALTER CASING	☐		☐
MULTIPLE COMPLETE	☐		☐
CHANGE ZONES	☐		☐
ABANDON*	☒		☐
(other)			

5. LEASE
NM-37766
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
West Elephant Butte **RECEIVED**
8. FARM OR LEASE NAME
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Undesignated **WILDCAT**
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 7, T-12S, R-4W
12. COUNTY OR PARISH
Sierra
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4935' G.L.



(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

OIL & GAS
MINERALS SECTION SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/24/82 Ran 80 jts of 32 & 24# 3265' of 8 5/8" K-55, ST&C, R-3, A cond. csg. Set csg @ 3280', F.C. @ 3235', DV tool @ 1481'. Halliburton cmted 1st stage w/ 660 sacks of lite w/ 1/4# flocele, tail in with 200 sacks of "C". Containing 2% CaCl. Plug down @ 9:00 AM. Open DV, Circ 6 hours, 120 sacks 2nd stage 672 lite 1/4# flocele tail in w/ 100 sacks "C" containing 2% CaCl. Plug down @ 4:00 PM. Circ 260 sacks. Cut off & install head.
Received verbal approval to P & A West Elephant Butte Fed Well #1 from George Stewart with M.M.S. Roswell December 12, 1982.
12/10/82 Nipple down BOP. 1st plug 6850-7000', 60 sacks of Class "H", 2nd plug 3196-3328', 80 sacks of 2% CaCl tagged @ 3100'. 3rd plug 1331-1531, 30 sacks of class "H".
12/11/82 P&A. Nipple down, set 30' plug, 15 sacks & install dry hole marker. Release Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Glass TITLE Area Superintendent DATE December 13, 1982

APPROVED BY (ORIG. SGD.) DAVID R. GLASS TITLE _____ DATE _____
APPROVED BY JAMES A. GILLHAM TITLE DISTRICT SUPERVISOR DATE DEC 15 1982

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

12/10/82 Cont'd. rig @ 1:00 PM.