

RECEIVED

Form 1-331
(May 1984)

OCT 13 '87

Drawer DD

Roswell, NM 88216

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved:
Budget Bureau No. 42-R1171

5. LEASE DESIGNATION AND SERIAL NO.

LC-069280-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Sulimar Queen Unit

8. FARM OR LEASE NAME

Tract I

9. WELL NO.

11

10. FIELD AND POOL, OR WILDCAT

Sulimar Queen

11. SEC., T., R., W., OR BLK. AND
RANGE OR AREA

Sec. 24-T15S-R29E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether ft., m., etc.)

3958' G.L.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PUMP WATER SHUT-OFF

FRACTURE TREAT

ABANDON OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

ABANDON OR ACIDIZING

(Other)


REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)16. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

1. Pull packer and plastic line tubing out of hole. Ran working string in hole.
2. Loaded hole with viscous mud; Set 30 sx cement plug at 1980'; Tag TOC at 1800'.
3. Pulled tubing to 450', set 25 sx cement plug.
4. Pull tubing to 60' and circulate cement to surface. Pull out of hole and install dry hole marker.
5. Pumped 50 sx cement between 5-1/2" casing and 8-5/8" casing. Will clean location as soon as pit dries up.

Post ID-2
10-23-87
P4A

17. I hereby certify that the foregoing is true and correct

SIGNED

Paul Regalado

TITLE Operations Manager

DATE 3/24/86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
PETER W. CHESTER

OCT 6 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA