

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30.015.00676

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Empire Abo Unit "H"
2. Name of Operator BP America Production Company	8. Well No. 17
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	9. Pool name or Wildcat Empire Abo
4. Well Location Unit Letter M : 330' Feet From The S Line and 990 Feet From The W Line Section 36 Township 17S Range 27E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3641' RDB	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Workover ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 5797' PBD: 5794' PERFS: 5707-5784'

MIRUPU. POH w/rods & pump. NDWH. NUBOP.
RIH w/bit & scraper to PBTD @ 5794'. POH.
GIH & perf w/2 JSPF 5507-16', 5522-26', 5534-48', 5548-5604', 5616-18', 5622-26',
5633-40', 5647-70'.
GIH w/RBP, treating pkr & 2-3/8" tbg. Set RBP @ 5685'. Spot 169 gals 15% HCL NEFE f/
5670-5505'. PU & set treating pkr @ 5492'.
Acidize perfs f/5670-5507' w/6700 gals 15% HCL NEFE, dropping 3 ball sealers every
100 gals. Displace w/21 bbsl 2% KCL wtr.
Rlk pkr. RIH rls RBP @ 5685'. POH.
RIH w/prod. assy. Land SN @ 5754'. (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 07.09.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 11 2002

Empire Abo Unit H-17
Workover Procedures
30.015.00676

Notice of Intent Continued:

NDBOP. NUWH.
GIH w/GA, pmp & rds. Hang well on.
RTP