

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

LC 063578

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Southern Union Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Red Lake Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-16S-28E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Kincaid & Watson Drilling Company

3. ADDRESS OF OPERATOR

P.O. Box 498, Artesia, New Mexico 88211-0498

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

C. D.
ARTESIA, OFFICE

1980'/North, 1980'/East

Section 34-16S-28E, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3585' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We plugged this well as follows:

50 sacks cement 1491-1375.

25 sacks cement 685-590'.

50' plug to surface.

Loaded hole with jelled mud between plugs.

Cleaned up, ripped up and re-seeded location.

Set dry hole marker.

Aug 11 11 22 AM '88

RECEIVED

Post FD-2
8-26-88
P&A

18. I hereby certify that the foregoing is true and correct

SIGNED *Harvey King*

TITLE Secretary-Treasurer

DATE 8-3-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 8-16-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side