STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT	
RECEIVED BY ATION DIVISION  OISTRIBUTION  SANTA FE  V.S.G.S.  LAND OFFICE  OPERATOR  OPERATOR  RECEIVED BY ATION DIVISION  RECEIVED BY P. O. BOX 2088  SANTA FE, NEW MEXICO 87501  O. C. D.  ARTESIA, CELECE	Form C-103 Revised 10-1-7  Sa. Indicate Type of Leuse State Fee 5. State Oil 6 Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "PAPELICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
" WELL   GAS   OTHER Injection	7. Unit Agreement Name Red La Ice Prem
Kersey & Co. Red Lake Unit	8. Farm of Lease Name Sd. UT. Tr. 10
Box 316, AMESIA, N. Mey.	9. Well No.
UNIT LETTER . 2970  UNIT LETTER . 2310 FEET FROM THE SOUTH LINE AND 330 FEET FROM	10. Field and Pool, or Wildcat  Red Lake
THE WEST LINE, SECTION 28 TOWNSHIP 175 RANGE 285 NMPM	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CABING  CHANGE PLANS  CHANGE PLANS  CASING TEST AND CEMENT JQB	her Data T REPORT OF:  ALTERING CASING  PLUG AND ABANDONMENT
OTHER	· ,
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed
1. Put cement plug at 1600-1700'. Tag plug 1539'.	
2. Put cement plug in and out of casing Tol	7-800',
Tag plug 710!  3. Put coment plug 430-530!  Tag plug 300!	
4. Put cement plug at Surface	<b>A</b>
J. Set 4" Pipe Marker at Surface	1652 ID-2 3-21-86 1+A
TITLE CO-OWNEY	DATE NOV, 7, 1985
Davill Moore wie bedogsat	DATE 4/10/86