

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87508

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

MAY 26 1992

WELL API NO. 30-015-01715
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7116
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT " F "
8. Well No. 35
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240
4. Well Location Unit Letter <u>G</u> : 1965.68 Feet From The <u>EAST</u> Line and 1938.54 Feet From The <u>NORTH</u> Line Section <u>34</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3665' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
HOLD WELL BORE TO MONITOR BHP ANNUALLY  
TD 6300'; PBD 6100'; PERFS: 6054-6064'; PKR 5980'  
05/12/92 LOAD CSG w/8.6# BRINE w/WT-675 CHEMICAL, PRESSURE UP TO 540 # AND HOLD FOR 20 MINS. CHART ATTACHED. WITNESSED BY DERROLL WOLFENBARGER-ARCO AND GARY WILLIAMS-NMOCD.

This Approval of Temporary Abandonment Expires 5/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE James D. Cogburn TITLE Operations Coordinator DATE 5/21/92  
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 391-1600

(This space for State Use)  
APPROVED BY [Signature] TITLE Field Rep DATE 5/27/92  
CONDITIONS OF APPROVAL, IF ANY:

