

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 25 1991

WELL API NO. 30-015-01733
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "F"
8. Well No. 38
9. Pool name or Wildcat EMPIRE ABO

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240

4. Well Location Unit Letter <u>F</u> : <u>1650</u> Feet From The <u>NORTH</u> Line and <u>1650</u> Feet From The <u>WEST</u> Line Section <u>35</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3691' KB</u>
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>TEMPORARILY ABANDON</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6404', PERFS: 6246-6254'

4-08-91 MIRU. DDP. ND WH NU BOP. ATTEMPTED TO UNSET PKR. WORKED w/PKR. WOULD NOT COME UNSET. UNSCREWED MANDREL FROM PKR. POH w/TBG, KOBE CAVITY, AND PKR MANDREL. SET UP REVERSE UNIT TO DRILL OUT PKR. SDON.

4-09-91 R.O. PICKUP RIH w/4-3/4" BIT, SUB AND 4 D.C. RIH w/TBG. RU POWER SWIVEL AND CIRCULATING UNIT. DRILL OUT PKR. RIH w/REMAINDER OF TBG. PUSH PKR TO BOTTOM. POH w/TBG, D.C. AND BIT. RIH w/4-3/4" BIT, 5-1/2" CSG SCRAPER.

4-10-91 R.O. RIH w/CIBP, RUNNING TOOL, AND TBG. SET CIBP POH w/1 JT TBG. RU KILL TRUCK. CIRCULATE WELL w/8.6# BRINE w/WT-675 CHEMICAL. CLOSE IN BOP. PRESS UP TO 540#. HOLD FOR 15 MINS. POH w/TBG & RUNNING TOOL. LAYING TBG DOWN IN SINGLES. LEFT 1 JT ON WELLHEAD FLANGE. CIBP SET @ 6218.30'. PRESSURE TEST

I hereby certify that the information above is true and complete to the best of my knowledge and belief. ATTACHED. TEST WITNESSED BY GARY WILLIAMS, NMOC

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 4/24/91
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 4/29/91

CONDITIONS OF APPROVAL, IF ANY: