	NEW MEXIC Shell Oil Company Henshaw - Wolfcomp	CO OIL CONSERVATION COMMIS P. O. Box 18 ADDRESS <u>Reswell, New</u> LEASE <u>Federal GA</u>	58 (1. ⁵) (1. ¹)
LOCATION	1980' FSL & 660' FR New Maxico	L. Section 22, T-16-S, R-	30-R. MPM Survey, Rody County,
140' 275' 300' 325' 420' 450'	1/4 deg. 1/4 deg. 1/4 deg. 1/4 deg. 1/4 deg. 1/2 deg. 1/4 deg. 1/4 deg.	DEVIATION RECORD 4880' = 1/4 deg. 5050' = 1/2 deg. 5212' = 1/2 deg. 5344' = 1 1/4 deg. 5490' = 2 deg. 5691' = 1 1/2 deg. 5880' = 1 1/4 deg. 6090' = 1 3/4 deg.	9150' = 3 3/4 deg. 9310' = 4 1/4 deg. 9470' = 3 1/2 deg.
1000* - 1250* - 1500* - 2000* -	3/4 deg. 3/4 deg. 1 deg. 1 1/4 deg.	6297' = 2 deg. 6430' = 1 deg. 6648' = 2 deg. 6800' = 1 3/4 deg.	RECEIVED JUL 1-6 1964
2360'	1 1/2 deg. 1 3/4 deg. 1/2 deg. 1 deg. 2 deg.	6925' = 1 3/4 deg. 7015' = 2 1/4 deg. 7150' = 2 1/2 deg. 7375' = 3 1/4 deg. 7615' = 4 deg. 7810' = 4 deg.	D. C. C. ARTESIA, OFFICE
3525' = 3975' = 4185' = 4325' = 4472' =	1 3/4 deg. 1 1/4 deg. 2 deg. 2 deg. 1 3/4 deg. 1 1/2 deg. 1/4 deg.	7950' = 4 deg. 8120' = 3 1/4 deg. 8510' = 3 1/4 deg. 8630' = 2 3/4 deg. 8700' = 2 3/4 deg. 8740' = 3 1/4 deg. 9020' = 3 1/2 deg.	

Certification of personal knowledge of Deviation Record:

I hereby certify that I have personal knowledge of the data and facts placed on this form, and that such information is true and complete.

King Signature Company

STATE OF NEW MEXICO COUNTY OF CHAVES

Before me, the undersigned authority, on this day personally appeared <u>V. L. King</u>, known to me to be the person whose name is subscribed hereto, who, after being duly sworn, on oath states that he is acting at the direction and on behalf of the operator of the well identified in this instrument and that such well was not intentionally deviated from the vertical.

Signatur

Acting District Exploitation Engineer

Sworn and Subscribed to before me, this the _____day of _____July _____,1964-

MY COMMISSION EXPIRES FEBRILARY 7 1015

Notary Public in and for Chaves County,