

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE  
(Other instructions on reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS USED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
EAGLE OIL & GAS CO.

3. ADDRESS OF OPERATOR  
510 HAMILTON BLDG., WICHITA FALLS, TX 76301

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface  
1980' FSL & 660' FEL

14. PERMIT NO.  
NA

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
GR @ 3587', KB @ 3605'

16. PERMIT NO.  
NA

17. ELEVATIONS (Show whether DF, RT, GR, etc.)  
GR @ 3587', KB @ 3605'

5. LEASE DESIGNATION AND SERIAL NO.  
8940-NM

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
NA

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
CROW FLATS "A" FEDERAL

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
SEC 19-T16S-R28E

12. COUNTY OR PARISH  
EDDY

13. STATE  
NM

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) RECOMPLETION ATTEMPT ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/10/90 THRU 12/19/90

SET CIBP @ 6325' & CAPPED W/ 35' PREMIUM CMT. CUT & PULL 4-1/2" CSG @ 4800'. RIH W/ TBG TO 4875'. CIRC HOLE W/ GEL BRINE. SPOT 60 SX PREMIUM CMT PLUG. WOC. TAG PLUG W/ DEPTHOMETER @ 4690' - 110' ABOVE STUB. SET 8-5/8" 24# CIBP @ 2000' & CAPPED W/ 35' PREMIUM CMT. RAN TBG TO 1600' & SWABBED DRY. PERF'D 1762-68' & 1754-60' W/ 4 JSPF W/ 4" CSG GUN. RIH W/ MUD ANCHOR, PERF'D SUB + SN ON 58 JTS TBG W/ SN @ 1815'. STARTED SWAB TESTING. RESULTS DISCOURAGING. NO FLUID ENTRY. POH & ACIDIZE W/ TBG & PKR W/ 3000 GAL 15% NEFE HCL + 60 BALLS. STARTED SWAB TESTING UNDER PKR. RESULTS DISCOURAGING. PUT WELL ON PUMP TO RECOVER LOAD & EVALUATE PRODUCTION.

1/28/90

WELL IS SHUT IN. HAS NEVER RECOVERED TOTAL ACID LOAD. NO FLUID ENTRY. PLAN TO PLUG AND ABANDON.

18. I hereby certify that the foregoing is true and correct

SIGNED

JIM CRANDALL

TITLE PETROLEUM ENGINEER

DATE 1/28/91

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD  
DATE

FEB 6 1991

SJS

\*See Instructions on Reverse Side

Title 16 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CARLSBAD NEW MEXICO