Form 3160-5 November 19	19-21 TT RR21()	U! ED STATE			re• Bude	approved. get Bureau No. 1(res August 31, 19	C/1 7 004-0135	
Formerly 9-	331) DEPART	MENT OF THE AU OF LAND MANA		(verse side)	5. LEASE I	DESIGNATION AND SI 0420 (a)		
(Do no	SUNDRY NO	TICES AND REP	ORTS ON	WELLS to a different reservoir.	6. IF INDIA	AN, ALLOTTEE OR TE	IIBE NAME	
1.		KECCIVED 0				REEMENT NAME		
OIL X WELL X	WELL OTHER	MAY 0 = 198	4		1 -	7 Unit		
<u> </u>	1		,	The second secon				
	Getty Oil Company 3. Address of OPERATOR		·E 6			9. WELL NO. 25		
P.O. I	Box 730, Hobbs	ARTESIA, OFFIC		e requirements *		AND POOL, OR WILD	OC LT	
See also space 17 below.) At surface			e with the police	e requirements.	1	Grayburg Jackson 🐙 🖅 🚶		
Ur	nit Ltr.I, 1980	FSL & 66C FEL			11. SBC., 1 SUB	., R., M., OR BLK. AN VEY OR AREA	no ,	
					Sec.	15, T-17S,	R-31E	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3878 DF			1	12. COUNTY OR PARISH 13. STATE Eddy NM		
16.	Check A	Appropriate Box To I	ndicate Natu	re of Notice, Report, o	or Other Data			
	NOTICE OF INT	ENTION TO:				CENT REPORT OF:		
TEST WAT	TER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL		
FRACTURE	TREAT	MULTIPLE COMF+ ETE		FRACTURE TREATMENT		ALTERING CASING		
SHOOT OR		ABANDON*		SHOOTING OR ACIDIZING	X	ABANDONMENT*		
REPAIR W (Other)	ELL	CHANGE PLANS		(Other)(Nore: Report res	uits of multiple	completion on We	-i	
17. DESCRIBE I	ROPOSED OR COMPLETED Of work. If well is directhis work.)*	PERATIONS (Clearly state tionally drilled, give subs	all pertinent de surface locations	Completion or Rec- tails, and give pertinent de and measured and true ve			tarting any sones perti-	
4/10/84 T 4/11/84 T 3 f 4/12/84 B 3 3	IH w/ 3 7/8" bi ill). Drilled IH w/ 3 7/8" bi 630'. TOH. TI rom 3240-3545'. y Dowell spot 2 545' w/ 5500 ga	8' - 3508-3516 t, 4 - 3 1/8" I H w/ 4 1/2" Art Set pkr. @ 31 210 gals 15% NEFE & 5 d, A.I.R. 51 BP	sg. scrape '. Circ. DC's on 2 row 32-A r 165'. Pur FE from 35	er on 2 3/8" tbg. hole clean. TOF 3/8" tbg. Tagge okr. Spotted 245 mped 250 gals comped 250 gals comped 250 set pkm hecksol + 250 B.S. I to frac tank, in	d. ed @ 3516' 5 gals Nal nverter an r. @ 3101' 5. 200# in	co scale co d well went , acidize p crease on b	.4', 3516- onverter c on vacuum erfs 3240- oalls. Max	
· · t	bg. set @ 3533	•	ran 2" x	yed down pkr. T 1 1/2" x 12' RWH duction.		_	_	
SIGNED	Dale R. Crock	ett T	ITLE Area	Superintendent	DAT	April l	18, 1984	
(This space for Federal or State office use)					ACCEPTED	CCEPTED FOR RECORD		
APPROVED BY			ITLE		<u>ு புவ</u> ்.	1.25		
0+6 BLM-Ros		J.AMidland			\mathcal{M}_{\cdot}	4 4004		
1-File	l-Laura Richar	ason-Midland			MAY	1 1984		

*See Instructions on Reverse Side

1-JA, 1-Foreman EF, 1-Engr. PWS

1-BB