

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other information
reverse side)

Budget Bureau No. 1004-013
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
LC 029395 (a)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
ARCO Oil and Gas Company
3. ADDRESS OF OPERATOR
P. O. Box 1610, Midland, Texas 79702
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
330 FSL & 1398 FWL (Unit N)

RECEIVED BY

DEC 12 1986

O. C. D.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Fren Seven Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-17S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

14. PERMIT NO.

API 30-015-05223

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3743 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

RU PU 7-1-86. P&A as follows:

Plug	Interval	Cmt	Remarks
1	1340-1900	115 sx "H"	CIBP w/560' cmt. (OH plug)
2	550-1350	174sx "H"	Perf @ 1340. Could not pump into. Spot 174sx. (Salt)
3	0-560	209 sx "H"	Perf @ 560. Cmt inside & outside 7" csg.

Cut off wellhead. Install dryhole marker. Level & seed location.
P&A'd 7-2-86.

18. I hereby certify that the foregoing is true and correct

SIGNED Ken W. Gosnell

915-688-5672
TITLE Engr. Tech. Spec.

DATE 12-3-86

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

TITLE

DATE

Post ID-2
12-19-86
P&A

*See Instructions on Reverse Side