

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. CATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "B"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

20-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR SINCLAIR OIL & GAS COMPANY	
3. ADDRESS OF OPERATOR P. O. Box 1920, Hobbs, New Mexico 88240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' fr the North line and 660' from the West line	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3666' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Convert oilwell to WIW

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Total Depth 3432'. Completed in Grayburg Jackson Open Hole interval 2890-3432' presently producing 5 BOPD and 0 BWPD.

PROPOSE TO: Clean out to T.D. if necessary. Run 2-3/8"OD tubing and packer set @ approx. 2815'. Convert from oilwell to water injection well in Grayburg Jackson Open Hole interval 2890-3432' in Russell-Turner Waterflood Area.

RECEIVED
NOV 2 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Tom Henderson

TITLE

Engineer

DATE

10-31-67

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DATE

NOV 2 1967

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Orig&4cc: USGS, Artesia, N.M.
cc: Regional Office
cc: file