May 1963) JINITED STATES SUBMIT UPLICATE One on r GEOLOGICAL SURVEY			
			10 02023510 Mars 6
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
i. OIL X GAS WELL Shut-In 2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
Atlantic Richfield Company 3. ADDRESS OF OPERATOR			Turner "B" 🔀
P. O. Box 1978, Roswell, New Mexico 88201			9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			Fren-7 Rivers
1980' FSL & 1980' FEL			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T17S, R311
14. PERMIT NO.	15. ELEVATIONS (Show whether 3685 DF	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Eddy N.M.
		Nature of Notice, Report, or	
TEST WATER SHUT-OFF	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	QUENT REPORT OF: BEPAIRING WELL ALTERING CASING
SHOOT OR ACIDIZE REPAIR WELL (Other)	ABANDON* CHANGE PLANS		ts of multiple completion on Well pletion Report and Log form.)
17. DESCRIBE PROLOGED OF COMPLETED C proposed work. If well is directed to this work.) *	PERATIONS (Clearly state all pertin tonally drilled, givesurface lo	ent details, and give pertinent date cations and measured and true vert	s, including estimated date of starting any local depths for all markers and zones perti-
is no lo	nger economical t	April, 1971, beca to produce. This future waterflood.	use the well well is
R	ECEIVED MAY 27 1971	RECE	
	O. C. C. TESIA, OFFICE	MAY 25 I D. S. GEOLOGIA ARTESIA, NEW	Jakas da Bara
18. I hereby certify that the roregoing	As true and correct	Dist. Drlg. Superv	isor 5/24/71
(This space for Federal or State	office use)		

*See Instructions on Reverse Side