Form 9-331 (May 1963)

N. M. O. C. C. LUPT

SUBMIT IN

JCATE* on reForm approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

	GEOL	OGICAL	. SURVEY			
CHINIDDA	NOTICES	AND	DEDORTS	ON	WFI	ı

ITED STATES

DEPARTMENT OF THE INTERIOR (Other instruerers side)

SUNDKY MOTICES AND KELOKIS ON MELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT-" for such proposals.)

			 			 	7.	UNIT	Ā	GRE	EМ	ENT	NAS	ΙE	_
-	_	-	•		-										
		-		,	-										

	OIL GAS WELL OTHER		RECEIVED	
2.	NAME OF OPERATOR			8. FARM OR LEASE NAME
	Atlantic Richfield Company	, Marie Control	DCC 6 1974	Turner "B" SP
3.	ADDRESS OF OPERATOR		DEC 0 13/4	9. WELL NO.

P. O. Box 1710, Hobbs, New Mexico 88240 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface ARTESIA, OFFICE

10. FIELD AND POOL, OR WILDCAT

1980' FSL & 1980' FEL (Unit letter J)

Fren Seven Rivers 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA

20-17S-31E 13. STATE 12. COUNTY OR PARISH

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 3685'DF

N.M.

16.


ACTING DISTRICT ENGINEER

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOT	ICE OF	INTENTION TO:		Į.	SUBS	EQUEN.	I REPORT OF .		
			$\overline{}$		1				1
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OF	f e		REPAIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE	_	FRACTURE TREA	TMENT		ALTERING CASING		
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR A	CIDIZING		ABANDONMENT*		
REPAIR WELL		CHANGE PLANS		(Other)	Shut	in		x	
REPAIR WELL		CHANGE THE		(NOTE: R	teport resu	ilts of	multiple completion on Wel	1	
(Other)				Completic	on or Reco	m pletic	on Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was shut in during the month of April, 1971. The well was shut in because it was uneconomical to produce. This well is a secondary recovery prospect after deeper waterflood is completed in 8 to 10 years.



18. I hereby certify that the fore	going is true and corr	TITLE Dist. Prod. & Dr	lg. Supt.	DATE October 31, 1
(This space for Federal or S				DATE
APPROTED BY APPROVA	L, IF ANY:	*See Instructions on Reverse Side		DATE
DEC 5 1371	BE PUT TO BELLE	*See Instructions on Reverse Side		