

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN _____
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029419 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

* *

7. UNIT AGREEMENT NAME

Shelly Unit

8. FARM OR LEASE NAME

Shelly Unit

9. WELL NO.

51

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC. T. R. S. OR BLK. AND
SURVEY OR AREA

Sec. 22-17E-31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR Shelly Oil Company	3. ADDRESS OF OPERATOR Box 730 - Hobbs, New Mexico	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1900' FSL and 660' FSL Section 22-17E-31E	14. PERMIT NO. -	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3851' D.F.
--	---	---	--	---------------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Clean out and perforate ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Moved in, rigged up workover unit, pulled rods and tubing.
2. Drilled bridge plug at 3500' and cleaned out to 3020'.
3. Washed open hole 3020-3020' with 500 gallons regular 15% acid.
4. Perforated 8-5/8" OD casing with one shot per interval at the following depths: 3219', 3227', 3243', 3288', 3325', 3345', 3364', 3376', 3393', 3401', 3446', 3450', 3461', 3500', 3590', 3606', a total of 16' and 16 shots.
5. Treated 8-5/8" OD casing perforations 3500-3606' with 500 gallons regular 15% acid.
6. Treated 8-5/8" OD casing perforations 3446-3461' with 500 gallons regular 15% acid.
7. Treated 8-5/8" OD casing perforations 3219-3401' with 10000 gallons with 300 lbs. J-2, 50 gallons Solusol 14-A and 100000 20/40 sand.
8. Ran rods and tubing and installed pumping equipment.
9. Pumped and tested. Well pumped 16 barrels oil and 10 barrels water in 24 hours.

RECEIVED

JUL 21 1967

18. I hereby certify that the foregoing is true and correct.

SIGNED

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DISTRICT ENGINEER

TITLE

DATE July 19, 1967

JUL 20 1967

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847-831