

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY N. M. O. C. C. COPY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form Approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER **Injector**

2. NAME OF OPERATOR **RECEIVED**
Getty Oil Company

3. ADDRESS OF OPERATOR **P. O. Bcx 730; Hobbs, New Mexico 88240**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface **Unit F, 1980 FNL and 1980 FWL**

5. LEASE DESIGNATION AND SERIAL NO. **IC - 029418 (A)**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME **Skelly Unit**

8. FARM OR LEASE NAME

9. WELL NO. **48**

10. FIELD AND POOL, OR WILDCAT **Grayburg-Jackson**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA **23-17S-31E**

12. COUNTY OR PARISH **Eddy** 13. STATE **N.M.**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) **3870' DF**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) **xxx - Bring cement top up**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
1. Pull tubing and pkr.
 2. Run cement bond log.
 3. Perforate and bring cement top above 7-Rivers.
 4. Run temperature survey.
 5. Rerun tubing and pkr.
 6. Place well back on injection.

RECEIVED
AUG 90 1977
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE Area Superintendent DATE August 9, 1977

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ADDITIONAL
AUG 10 1977
R. L. [Signature]
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side