Form 3160-5 U November 1983) Formerly 9-331) BUREAU	T T TRIPLICATION OF THE PROPERTY OF THE PROPER	LC-029020 (g) 0. 15 INDIAN, ALLOTTEE OR TRIDE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			7. UNIT AGREEMENT NAME	
OIL X CAS OTHER			8. FARM OR LEASE NAME	
2. NAME OF OPERATOR			DEXTER	
ARROWHEAD OIL CORPORATION CORPORATION RECEIVED			9. WELL NO.	
3. ADDRESS OF OPERATOR P.O. BOX 548, ARTESIA, NEW MEXICO 88210				2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* MAY 27 '88 At surface			Grayburg Jackson R-Q-(
2310' FWL & 2310' FSL C. C. D. ARTESIA, OFFICE			Sec.22-T17S-R30E	
14. PERMIT NO. 30-015-10220	15. ELEVATIONS (Show whether D	op, mt, GR, etc.)	12. COUNTY OF PARISH	NM NM
16. Check App	ropriate Box To Indicate I	Nature of Notice, Report, or (Other Data	·
NOTICE OF INTENTI TEST WATER SHUT-OFF PU FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WILL (Other) 17. DESCRIBE PROPUSED OR COMPLETED OPERA Proposed work. If well is directions	ON TO: LL OR ALTER CASING PLTIPLE COMPLETE ANDON* ANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Pull rod/ (Note: Report result Completion or Recomp	ALTERING C. ABANDONMEN tbg. chem Sql s of multiple completion Report and Log for	ASING
nent to this work.)* $5-1-88$	Propose to posqueeze and	ull rods & tbg. an put on pump.	d do chemica	1
5-9-88	Pull rods & put well on	tubing, did chemic production.	al squeeze,	and
		* •	••	
			•	
A)	<i>j</i>			
18. I hereby certify that the foregoing is	true and correct	Dundantion Olamb	5/	12/88
SIGNED FIGURE Production Clerk			DATE	
(This space for Federal or State office	usey	.•		
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:			DATE	

Form approved.