

Form 3160-5 (November 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM A	PPRO	VED
OMB No.	1004	-0135
Expires Ju	lv 31.	1996

C158

## **SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. LC-031844

6. If Indian, Allottee or Tribe Name

		ruj idi sucii proposais.	
SUBMIT IN TRI	IPLICATE - Other ins	ructions on reverse side	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Weil  Oil Well  Gas Weil  KOther  SWD		FREN OIL CO COM	
2. Name of Operator MARBOB ENERGY CO	<u>, , , , , , , , , , , , , , , , , , , </u>		8. Well Name and No. FREN OIL CO COM #21  9. API Well No.
3a. Address P.O. BOX 227, AR	3b. Phone No. (include area code) 505-748-3303		30-015-10610
4. Location of Well (Footage, Sec.,	·		10. Field and Pool, or Exploratory Area CEDAR LAKE (MORROW GAS)
	, SEC. 19-T17S-R3		11. County or Parish, State  EDDY CO., NM
12. CHECK AP	PROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	OTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF AC	
Notice of Intent  Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Practure Treat Reclar Record R	water Shut-Off  amation  Well Integrity  mplete  Water Shut-Off  CLEAN OUT
Final Abandonment Notice	Convert to Injection		porarily Abandon or Disposal
Attach the Bond under which the following completion of the invotesting has been completed. Findetermined that the site is ready for the following the follo	e work will be performed or polyed operations. If the operations all Abandonment Notices shall for final inspection.)	rovide the Bond No. on file with BLM/B	ng date of any proposed work and approximate duration thereof ured and true vertical depths of all pertinent markers and zones BIA. Required subsequent reports shall be filed within 30 days completion in a new interval, a Form 3160-4 shall be filed once luding reclamation, have been completed, and the operator has

RU, TOH W/PKR, TIH W/ 6 1/8" BIT & COLLARS, CLEAN OUT OPEN HOLE, TOH, LD COLLARS, TIH W/PKR, SET PKR @ 12253', DISPLACE HOLE W/PKR FLUID, RUN 30 MINUTE INTEGRITY TEST TO 300# - HELD OK. PUT BACK ON INJECTION. SEE CHART ATTACHED. (NOTIFIED BETTY ROLLINS @ OCD).

