

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILZ	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

APR 6 1982

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	647-368

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company /	Empire South Deep Unit
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	8. Farm or Lease Name Empire South Deep Unit
4. Location of Well UNIT LETTER <u>H</u> <u>2280</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17-S</u> RANGE <u>28-E</u> NMPM.	9. Well No. 19
15. Elevation (Show whether DF, RT, GR, etc.) 3692.9 RDB	10. Field and Pool, or Wildcat Und. Empire South Wolfcamp
12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon the Cisco Canyon and recompleate in the Wolfcamp per the following:  
Pull rods, tubing, pump, and retrievable bridge plug. Run in hole with CIBP and set at 8765' and cap with 35' of cement. Perforate intervals 7730-40 with 4 JSPF. Run in hole with tubing and packer and swab test well. Acidize well if necessary and swab test.

0+4-NMOCD, A 1-Hou 1-W. Stafford, Hou 1-DMF 1-Depco 1-Yates, A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Freeman TITLE Assist. Admin. Analyst DATE 3-17-82  
APPROVED BY W. C. Gressett TITLE SUPERVISOR, DISTRICT II DATE APR 16 1982  
CONDITIONS OF APPROVAL, IF ANY: