

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-0-15-00185
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name ATOKA SAN ANDRES UNIT
8. Well No. 138
9. Pool name or Wildcat ATOKA SAN ANDRES

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection	
2. Name of Operator PENNZOIL EXPLORATION & PRODUCTION COMPANY	
3. Address of Operator P O BOX 50090 MIDLAND TEXAS 79710-0090	
4. Well Location Unit Letter <u>E</u> : <u>1680</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>13</u> Township <u>18S</u> Range <u>26E</u> NMPM <u>EDDY</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU PU.

POOH W/RODS. TEST CASING FROM SURF. TO CIBP @ 1478' TO 500#. ND WH AND NU BOP.

RIH W/3 7/8" BIT AND BHA ON 2 7/8" WS. DRILL OUT CIBP @ 1478' AND PUSH TO PBTD @ 1760'. POOH W/BIT, BHA & WS.

PERFORATE SAN ANDRES 1586-92', 1607', 1684', & 1722-30' W/2 JHPF (36 HOLEST).

ACIDIZE SAN ANDRES PERFS W/4800 GALS OF 15% NEFE HJ ACID.

SWAB ACID WTR. RD SWAB EQUIPMENT.

POOH AND LD 2 7/8" WS AND PKR.

RIH W/2 3/8" PRODUCTION TBG.

ND BOP, NU WH. CONNECT SURF LINES.

RETURN WELL TO INJECTION. RDMO PU. CLEAN LOCATION

RECEIVED

NOV 30 1995

OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon Hindman TITLE Production Assistant DATE 11/29/95
TYPE OR PRINT NAME Sharon Hindman 915 686-3505
TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 7 1995