			1	
Submit 3 Copies To Appropriate District	State of New Mexico		C15100	Form C-103
Office	Energy, Minerals and Natural Resources		Revis	ed March 25, 1999
<u>District I</u> 1625 N. French Dr., Hobbs, NM 87240	Zilorgj, iriniorais and iracatal recomines		WELL API NO	
District II	OIL CONSERVATION DIVISION		30-015-00211	
811 South First, Artesia, NM 87210 District III	2040 South Pacheco		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗖 F	EE 🔯
District IV	Santa Fe, INIVI 8	/303	6. State Oil & Gas Lease	No.
2040 South Pacheco, Santa Fe, NM 87505				
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON WELLS	HARRY TO A	7. Lease Name or Unit A	greement Name:
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM 6, 101) F	OR SUCH A		
PROPOSALS.)	/23	<b>A</b> (2)		
1. Type of Well:			West Dayton	
Oil Well X Gas Well [	$\Box$ Other $\langle \mathcal{E} \rangle$	<del>2001 S)</del>	8. Well No.	
2. Name of Operator  Read & Stevens, Inc.	/ REC	ELYED 66	8. Well No.	
3 Address of Operator	- \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	RIESIA	9. Pool name or Wildcat	
•	well, NM 88202	3.7	Penasco Draw San A	ndres Yeso Assoc
4. Well Location	N. Pres.	100		
100000000000000000000000000000000000000				
Unit LetterP:_	990 feet from the Sout	h line and	feet from the	East line
0 10	T 1: 100 P	0.6-	\n_m\4	
Section 19		inge 26E	NMPM County	/ Eddy
10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3,442' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF IN				٥٢.
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	SEQUENT REPORT	
PERFORM REMEDIAL WORK	PLOG AND ABANDON	REMEDIAL WOR	ALIER	RING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII	LING OPNS. PLUG	AND $\Box$
			ABANI	DONMENT
PULL OR ALTER CASING L	MULTIPLE	CASING TEST AN	ID 🖂	
	COMPLETION	CEMENT JOB		
OTHER:		OTHER: I	Re-entry	$\overline{\mathbf{X}}$
12 Describe proposed or complete	d operations. (Clearly state all per	tinent details, and g	ive pertinent dates, including	estimated date
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.	•	•		1
04/25/01 MIRUPU. PU 7 5/8" milled tooth bit and drill out cmt plugs, RIH to 1,800'.				
Run 40 jts 4 ½" 11.6# J-55 ST&C csg and set @ 1,782', float collar @ 1,737'. Cmt w/				
250 sx Class "C" cmt. WOC, run GR/CBL/CCL from 1,730' to 600', found TOC @ 750'.				
Perf 1,470'-88' and 1,506'-26' w/ 2 spf. Acidize w/ 1500 gal 15% NEFe, had show of oil.				
Frac well w/ 80,000# of 16/30 sand carried in 30# cross linked gel. Recover load, pump test 2 BOPD, 8 BWPD, gas TSTM.				
pump test 2 BOPD, 8	BWPD, gas ISIM.			
				•
	and pull pump and tbg. F			
	and pull pump and tbg. Fize perfs w/ 1000 gal of 1			
	ize perfs w/ 1000 gal of 1			
RBP @ 1,345'. Acid	ize perfs w/ 1000 gal of 1			
RBP @ 1,345'. Acid and cleaning up. RDI	ize perfs w/ 1000 gal of 1 MOSU.	5% NEFe. Sv	vab load, well flowing	
RBP @ 1,345'. Acid	ize perfs w/ 1000 gal of 1 MOSU.	5% NEFe. Sv	vab load, well flowing	
RBP @ 1,345'. Acid and cleaning up. RDI	ize perfs w/ 1000 gal of 1 MOSU.	5% NEFe. Sv	vab load, well flowing	g gas
RBP @ 1,345'. Acid and cleaning up. RDI  I hereby certify that the information of the signature of the signature of the signature.	ize perfs w/ 1000 gal of 1 MOSU.  above is true and complete to the b	5% NEFe. Sv	vab load, well flowing	g gas
RBP @ 1,345'. Acid and cleaning up. RDI  I hereby certify that the information of the signature of the signature of the signature.	ize perfs w/ 1000 gal of 1 MOSU.  above is true and complete to the b  TITLE  Maxey. Jr.	est of my knowledg  Operations M	e and belief.  DATE	g gas
RBP @ 1,345'. Acid and cleaning up. RDI  I hereby certify that the information of the signature of the signature of the signature.	ize perfs w/ 1000 gal of 1 MOSU.  above is true and complete to the b  TITLE  Maxey. Jr.	est of my knowledg  Operations M	e and belief.  DATE	g gas 7-5-01
RBP @ 1,345'. Acid and cleaning up. RDI  I hereby certify that the information of SIGNATURE  Type or print name  John C.  (This space for State use)	above is true and complete to the b	est of my knowledg  Operations M	e and belief.  Anager DATE  Telephone No.	7-5-01 505/622-3770 Ext 224
RBP @ 1,345'. Acid and cleaning up. RDI  I hereby certify that the information of the signature of the signa	ize perfs w/ 1000 gal of 1 MOSU.  above is true and complete to the b  TITLE  Maxey. Jr.	est of my knowledg  Operations M	e and belief.  DATE	g gas  7-5-01  505/622-3770