

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

RECEIVED

WELL API NO. 30-015-00903
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-10456
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "R"
8. Well No. 6
9. Pool name or Wildcat EMPIRE ABO
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3498' DF

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ARCO Permian
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240	4. Well Location Unit Letter F : 1650 Feet From The NORTH Line and 1650 Feet From The WEST Line Section 16 Township 18S Range 27E NMPM EDDY County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3498' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: DRILL OUT PLUGS, PERF ABO, ART LIFT ☐

12. Describe Proposed or Completed Operation (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 5700' PBD: 5673' PERFS 5498-5600'

05/15/94

DRILL CMT PLUG 1452' TO 1560', DRILL OUT PLUG @ 1620', DRILL CMT 5090-5215', DRILL CMT 5345-5380', DRILL CMT 5380' TO CR @ 5408'. DRILL 5526-5649' PERF ABO 5498-5600' W/2 JSPF TOTAL 145 HOLES. ACIDIZE ABO PERFS 5498-5600' W/3650 GALS NEFE 15% ACID. RIH W/CA, PUMP, & RODS. LOAD TUBING & PRESS UP TO 500#. GOOD PUMP ACTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE RECORDS CLERK II DATE 08/02/94  
TYPE OR PRINT NAME KELLIE D. MURRISH TELEPHONE NO. 391-1649

(This space for State Use)

SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE SEP 6 1994  
CONDITIONS OF APPROVAL, IF ANY: