

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

EC 058382

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ballard Grayburg
San Andres Unit

8. FARM OR RANCH NAME

Tract No. 11

9. WELL NO.

2

10. LOCATION OF WELL (See also space 17 below.)
At surface

Loco Hills, Queen
Grayburg San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR APP.

6 - 18 - 29E

12. COUNTY AND PARISH

Eddy New Mexico

1. ☒ OIL
WELL ☐ GAS
WELL ☐ OTHER

2. NAME OF OPERATOR

Amstarco Production Company

3. ADDRESS OF OPERATOR

P. O. Box 67, Loco Hills, New Mexico 88255

4. LOCATION OF WELL (See also space 17 below.)
At surface

990 PNL & 990 FEL SEC. 6, T18S, R29E
Eddy County, New Mexico

14. PERMIT NO.

15. ☒ Show whether DF, RT, GR, etc.)

3598 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Rigged up pulling unit, pulled rods, pump and tubing.
2. Cleaned out to old T. D. = 2715'; drilled additional Grayburg formation to 2830'.
3. Ran Gamma Ray Compensated Neutron Log.
4. Fracture treated Grayburg in 4 equal stages with a total of: 60,000 gals RF30, 1000 gals 15% NE acid, 24,000# 100 mesh sand, 50,000# 20/40 sand and 200# Gypban.
5. Reversed out frac sand; ran tubing, pump and rods.
6. Returned well to production.

Note: Production prior to Workover = 4 BOPD.
Production after Workover = 27 BOPD.

Copy of Log attached.

18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed by
Jerry E. Buckles

TITLE

Area Supervisor

DATE

Sept. 26, 1978

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACTING DISTRICT ENGINEER

DATE

SEP 29 1978

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.