5 - U.S.G.S. 1 - Admin. Unit, Mid land	
1 - Engineer (PWS' NMOC.D. COP	Form Approved.
Dec. 1973 1 - Foreman (LG) 1 - File UNITED STATES	Budget Bureau No. 42–R1424
DEPARTMENT OF THE INTERIOR	5. LEASE 9 LC 02941 8 (b)
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME RECEIVED Skelly Unit
reservoir. Use Form 9–331–C for such proposals.)	
1. oil gas development other Injection Well	9. WELL NO.V
2. NAME OF OPERATOR Getty Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Fren 7-R Graduckson SR-Q-G-S
P.O. Box 730, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec. 27, 17S, 31E
AT SURFACE: Unit ltr. B, 660' FNL & 1980' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	_ 14. API NO. 전성유회 문 전성유럽
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3824' DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3824 DF
TEST WATER SHUT OFF	이 가지 않는 것이 있는 것이 있다. 이 가지 않는 것이 있는 것이 가지 않는 것이 있는 것이 있는 것이 있는 것이 있다.
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING LI	change on Form 9–330.) c the second sec
CHANGE ZONES	· · · · · · · · · · · · · · · · · · ·
ABANDON* [] [] (other) Cement squeeze hole in casing.	· · · · · · · · · · · · · · · · · · ·
(0))··· <u>/</u>	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is of 	directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertine	Int to this work.)*
	한 실망님 한 · · 것 · · · · · · · · · · · · · · · ·
 Rig up pulling unit. Install BOP. 	가지 않는 것이 있는 것은 가지 않는 것이 있다. 이 가지 않는 것이 있는 것이 있는 것이 있다.
 Install BOP. POH with tubing and packers. 	이 맛있는 것은 한 것은 이 가지 않으며 이 것을 했다. 것은 것은 것은 것은 것은 것을 통하였다.
4. RIH with packer and bridge plug.	
5. Locate hole in 5 1/2" casing.	
6. Cement squeeze hole.	180, 180,
 Drill cut cement. Run tubing and packers. 	
10. Place well back on injection.	AV.
O L. C. O. C. A. Malan Manual Trans	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	endent _{DATE} April 6, 1981
Dale R. Crockett	
(This space for Federal or State o	A second s
APPROVED BY TITLE TITLE	
	APR 2 3 1981
*See Instructions on Reverse	
	JAMES A. GILLHAM DISTRICT SUPERVISOR

\$

RECEIVED

APR 2 2 1981

U.S. GEOLUGICAL SURVEY ARTESIA, NEW MEXICO