

1/91  
OP


**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

### OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505



WELL API NO. 30-015-27091
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. E-7811
Lease Name or Unit Agreement Name Cedar Breaks 2 State
Well No. # 1
Pool name or Wildcat Loco Hills Grayburg

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
 OIL WELL  GAS WELL  OTHER Water Injection

Name of Operator  
Mewbourne Oil Company

Address of Operator  
P.O. Box 5270 Hobbs, NM 88241

Well Location  
 Unit Letter G 2130 Feet From The North Line and 1980 Feet From The East Line  
 2 Section 18S Township 30E Range NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3629' GL

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-28-01 Spot 35 sxs @ 3060'-2578' (Tag)	Witnessed by MOC Rep. David Parsons
3-28-01 Circulate 10# Mud	
3-28-01 Spot 25 sxs @ 2150'-1641' (Tag)	Witnessed by MOC Rep. David Parsons
3-29-01 Perf @ 1400' Could not pump into perfs	Phil Hawkins w/ OCD on location
3-29-01 Spot 25 sxs @ 1450'-1250'	(Did not tag as per orders of OCD Rep. on location)
3-29-01 Pull 1000' of 5-1/2" casing	Phil Hawkins w/ OCD on location
3-29-01 Spot 30 sxs @ 1050'-926' (Tag)	Witnessed by MOC Rep. David Parsons & Phil Hawkins w/ OCD
3-30-01 Spot 35 sxs @ 598'-488' (Tag)	Witnessed by MOC Rep. David Parsons
3-30-01 Spot 10 sxs @ 30'-surface	Cut off wellhead and anchors

Install Dry Hole Marker

Revised  
12/91

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Burke TITLE Drilling Foreman DATE 04-09-01

TYPE OR PRINT NAME Terry Burke TELEPHONE NO. (505)393-5905

APPROVED BY [Signature] TITLE Field Rep DATE 1-30-02

CONDITIONS OF APPROVAL, IF ANY:

