

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

RECEIVED
SEP 23 1991

WELL API NO. 30-015-20593
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		O. C. D. ARTESIA OFFICE
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Matlock AJW	
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat Penasco Draw-Upper Penn	
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>Treat well/swab test</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-16-91. Clean location. Dig out cellar. Test anchors.
 9-17-91. RUPU. TOOH with 2-3/8" tubing. TIH w/bit and scraper to 7900'.
 9-18-91. Displaced hole from 7900' with 2% KCL. TOH with bit and scraper. TIH with 4 1/2" Uni V packer. Set packer at 7900'. Test casing below 1500#. Set packer at 7711'. Acidized existing perforations 7776-7816' with 10000 gals 20% NEFE acid Swabbed back. Total recovered 286 bbls with 5% oil cut (total oil approx. 15 bbls).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-20-91
 TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY
 MIKE WILLIAMS
 SUPERVISOR, DISTRICT II TITLE _____ DATE SEP 24 1991
 APPROVED BY _____
 CONDITIONS OF APPROVAL, IF ANY: _____