

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other: instruct cover sheet)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. LEASE DESIGNATION AND SERIAL NO. LC-065680

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Blackhawk Federal

9. WELL NO. 5

10. FIELD AND POOL, OR WILDCAT Shugart, Grayburg San Andres

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA Sec. 23: T18S, R31E

12. COUNTY OR PARISH Eddy

13. STATE NM

RECEIVED BY
DEC 3 1986
O.C.D.
OFFICE CHIEF

4. NAME OF OPERATOR Siete Oil & Gas Corporation

5. ADDRESS OF OPERATOR P. O. Box 2523, Roswell, NM 88201

6. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
2310' ^SFEL, 330" FEL NE/4 SE/4, Unit Letter I

14. PERMIT NO.

15. ELEVATIONS (Show whether SP, ST, OR, etc.) 3696' GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	FULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <u>Production Casing</u> <input checked="" type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/21/86 - L & M Rig #1 - T.D. 4500' @11:45 p.m. - condition mud & circ.

11/22/86 - TOH to log - RU Schlumberger - ran CNL - LDT - GR - CALIP - DLL - MSFL - Cyberlook - L & M Rig #1 ran 109 jnts (4505') of 5 1/2" 15.5# J-55 ST&C csg - set @4504'KB - float @4462.5 - marker jnt @4095' & 3610' - circ csg 15 min - cmtd csg w/690 sxs DLW III, 10# salt, 1/2# cello flake, tailed in w/300 sxs H.E. II, 5# salt, 1/2# cello flake, 5% fluid loss - P.D. @10:00 p.m. - Circ 50 sxs to pit - release rig @12:00 midnight - W.O.C.

ACCEPTED FOR RECORD
[Signature]
NOV 26 1986
CARLSBAD, NEW MEXICO

BUREAU OF LAND MANAGEMENT
RECEIVED
NOV 25 1986
DISTRICT OFFICE
CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE V.P. Drilling & Production DATE 11/24/86

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side