

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-27633

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Patriot AIZ Com

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.

3

2. Name of Operator
YATES PETROLEUM CORPORATION

RECEIVED

9. Well name or Wildcat

North Dagger Draw Upper Penn

3. Address of Operator
105 South 4th St., Artesia, NM 88210

FEB 24 1995

4. Well Location
Unit Letter P : 760 Feet From The South Line and 660 Feet From The East Line

OIL CON. DIV.

Section 20 Township 19S Range 23E NMPM Eddy County

10. Elevation (Show whether DF, RKB, AD) DIST. 2
3513' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: Add perforations & acidize <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-14-95 - Moved in and rigged up pulling unit. Nippled up BOP. TOOH with tubing, cable and sub-pump. Shut down.

2-15-95 - Rigged up wireline. TIH with 4" casing guns and perforated 7652-7668' w/14 .52" holes (2 SPF) as follows: 7652, 54, 56, 58, 60, 66 & 7668'. TOOH with casing guns and rigged down wireline. TIH with RBP, packer and 2-7/8" tubing. Set RBP at 7695' and tested to 2000 psi. Set packer at 7553' and tested annulus to 1000 psi. Acidized perforations 7652-7668' with 8000 gallons 20% NEFE gelled acid and ball sealers. Swabbing.

2-16-95 - Unset packer at 7553'. Unset RBP at 7695'. TOOH with tubing, packer and RBP. Released well to production to run sub-pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 2-23-95

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TIM W. GUM TITLE _____ DATE FEB 27 1995

CONDITIONS OF APPROVAL, IF ANY: