

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015- 20002 28592
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Patrick API
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 1
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat Dagger Draw Upper Penn, North
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>10</u> Township <u>19S</u> Range <u>25E</u> NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3505' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-31-95 - Cleaned location and set anchors. Moved in and rigged up pulling unit and reverse equipment. TIH with bit, stabilizer, drill collars and 2-7/8" tubing. Drilled DV tool at 6016'. Tested to 2000 psi. TIH and tagged PBTD at 8135'. Displaced hole with 2% KCL. TOOH and laid down drill collars. TIH with bit and scraper thru DV tool. TOOH. Rigged up wireline. Ran GR/CBL log.

11-1-95 - TIH with 2-7/8" open ended to 7885'. Spotted 250 gallons 20% HCl. TOOH with tubing. Rigged up wireline. TIH with 4" casing guns and perforated 7862-7870' w/5 .42" holes. TOOH with casing guns and rigged down wireline. TIH with 4" packer and set packer at 7796'. Opened by-pass. Reversed 5 bbls. Closed by-pass. Began swabbing.

11-2-95 - Bled well down. Swabbed. Loaded tubing. Released packer. TOOH. Rigged up wireline. TIH with 4" casing guns and perforated 7746-7840' w/25 .42" holes as follows: 7832-7840' w/5 holes and 7746-7802' w/20 holes. TOOH with casing guns and rigged down wireline. TIH with packer and RBP. Straddled perforations 7832-7840'. Broke perforations. Opened by-pass and spotted acid to packer. Closed by-pass. Pressured to 5000 psi. Communicated up. Moved packer and straddled perforations 7746-7840'. Acidized with 3500

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Production Clerk DATE 11-6-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ DATE _____

NOV 14 1995

