Oil Cons. N.M. DIV-[... 2 UNI'. STATES FORM APPROVED 1301 W. Grano Avehue OMB NO. 1004-0135 DEPARTMENT OF THE INTERIOR Artesia, NM 88210 Expires: November 30, 2000 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM-05551 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name RECEIVEDabandoned well. Use Form 3160-3 (APD) for such proposals. OCD - ARTESIA 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side NORTH INDIAN BASIN UNIT 1. Type of Well SIZLAN Well Name and No. Oil Well X Gas Well Other NORTH INDIAN BASINUNIT #8 2. Name of Operator Marathon Oil Company 9. API Well No. 3a Address 3b. Phone No. (include area code) 30-015-26324 P.O. Box 552 Midland, TX 79702 915/682-1626 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) INDIAN BASIN UPPER PENN UL "N", 330' FSL & 1650' FWL **EAS POOL** SECTION 9, T-21-S, R-23-E 11. County or Parish, State MM CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION X Acidize Notice of Intent Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Add Pay and Change Plans Plug and Abandon Temporarily Abandon Stimulate Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) 4/2/02 MIRU PU, ND wellhead & NU BOPs. POOH w/tbg, RIH w/bit and scraper and clean out hole. POOH and RIH w/3-1/8" perf guns to add new perfs 7524'-7581' and 7593'-7624' in 5 runs. POOH w/perf tools & RIH w/PPI packers To 7670'. Acidize new perfs w/100 gpf and existing perfs w/50 gpf, for a total of 12, 474 gals. 15% CCA sour acid. Flushed, fished valves, POOH w/PPI toold and LD. RIH w/tbg, ND BOPs, FU & RIH w/pump on original rod string. Long stroked pump and hung well off. Turned well over to production department 4/7/02 ACCEPTED FOR RECORD JUN 26 2002 ALEXIS C. SWOBODA PETROLEUM ENGINEER I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Ginny Larke Engineer Technician Date 6/25/02 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Office

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.