

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

cliff
op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28619
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> GAS Well <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Mojave AJY Com
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 3
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	9. Pool name or Wildcat Dagger Draw Upper Penn, South
4. Well Location Unit Letter <u>N</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>20 1/2 S</u> Range <u>23 E</u> NMPM <u>Eddy</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3717' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>Perforate & acidize</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-3-96 - Moved in and rigged up pulling unit. Nippled down wellhead and installed BOP. TOOH with 2-7/8" tubing and subpump. TIH with RBP and tubing to 7800'. Shut down.

1-4-96 - Rigged up wireline. Tried to set RBP - would not set. TOOH with tubing and RBP. Shut down.

1-5-96 - TIH with gauge ring and junk basket to 8200'. TOOH with gauge ring and junk basket. TIH with RBP and 2-7/8" tubing. Set RBP at 7762'. Tested RBP to 2500 psi. Spot 250 gallons 20% NEFE acid at 7760'. TOOH with 2-7/8" tubing. TIH with 4" casing guns and perforated 7742-7758' w/9 .42" holes as follows: 7742, 44, 46, 48, 50, 52, 54, 56 & 7758'. TOOH with casing guns and rigged down wireline. TIH with packer and tubing. Set packer at 7684'. Swabbing.

1-6-8-96 - Loaded tubing with 2% KCL water. Unset packer. Dropped down and unset RBP. Pulled up and rset RBP at 7714' and tested to 2500 psi. TOOH with tubing and packer. TIH with 4" casing guns and perforated 7688-7696' w/5 .42" holes as follows: 7688, 90, 92, 94 & 7696'. TIH with packer and 2-7/8" tubing. Set packer at 7633'. Acidized perforations 7688-7696' with 2000 gallons 20% NEFE acid and ball sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-9-96

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM DATE JAN 18 1996
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____