

AOP Well Procedure
ROBINIA DRAW UNIT NO. 2
East Walker Draw

CASING PROGRAM

Lease: _____

Well No.: _____

Intermediate - Drill a 12 1/4" hole to 2500'+ and set 8 5/8" casing..

AMOUNT	SIZE	PIPE REQUIREMENT WT./FT.	GRADE	CONNECTION
1800'	8 5/8"	24.0	K-55	ST&C
700'	8 5/8"	32.0	K-55	ST&C

CASING EQUIPMENT & PREPARATION

Run casing with a guide shoe, insert float with automatic fill, three centralizers, and 2 pounds thread compound.

Sandblast bottom 500 feet and clean threads.

CEMENT PROGRAM

Stage No.	Type & Additive Composition	Sl. WT. #/gal.	Sl. VOL. ft. ³ /sx.	Water gal./sx.	Pump Time	24 hr. Comp. St. psi @ degrees
950	Halliburton Light 5# Gilsonite 1/4# Flocele	12.2	2.04	11.2	4:00+	225 @ 110
200	Class C 2% CaCl	14.8	1.32	6.3	1:50	2680 @ 110

Remarks: _____