

Submit 3 Copies to Appropriate District Office

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Grande Rd., Aztec, NM 87410

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CIST
gr

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL AM NO. 30 015 23341

5. Indicate Type of Lease STATE FEE

6. State Oil & Gas Lease No. XXXXXXXX V-2627

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
MOSLEY SPRING "32"
STATE COM

1. Type of Well: OIL WELL GAS WELL OTHER

8. Well No. 2

2. Name of Operator Marks And Garner Production LTD Co

9. Pool name or Well Unit Und. Dark Canyon-Penn Gas

3. Address of Operator P O Box 70 Lovington NM 88260

4. Well Location Unit Lower N 660 Feet From The S Line and 2030 2-030 Feet From The W Line

Section 32 Township 23S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RRB, RT, GR, etc) 3824

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.
PULL OR ALTER CASING OTHER: CASING TEST AND CEMENT JOB
SUBSEQUENT REPORT OF:
ALTERING CASING
PLUG AND ABANDONMENT
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 9550 W/ 100 sacks cement on top(25 sacks)
Load hole w/ gel Spot 25sx cement Plug 8367: 8267.
Spot 25 sacks @ 6700' Perforate 4 1/2" @ 6700'. Syringe 100' cement Plug inside outside Csg. TAG
Shoot 5 1/2" @ free point appx 5500'
Spot 50 sacks in & out of stub--tag plug
Shoot 8 5/8" @ free point--appx 1000'
Spot 50 sacks in & out-Tag plug
Spot 25 sacks @ 396' 450: 350. TAG
Set dryhole marker w/ 10 sacks @ surface
* Spot 100' cement Plug 3100: 3000. TAG



* Notific N.M.O.C.D. To witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE James H. Buddy Garner TITLE Partner DATE 10-9-00
TYPE OR PRINT NAME James H. Buddy Garner TELEPHONE NO. 396-5326

(This space for State Use)
APPROVED BY David Stillfield TITLE Field Rep. II DATE 10/27/2000
CONDITIONS OF APPROVAL, IF ANY Note: Toc on 4 1/2" csg 7726 by Temp. Survey. 8 5/8" csg circulated to surface.

1953-1954
1954-1955
1955-1956

1956-1957

1957-1958

1958-1959

1959-1960