Form approved. Budget Bureau No. 1004-0135 UNITED STATES

SUBMIT IN TRIPLICATE*

Other Instructions on rerespectively. Ferm 3160--5 Expires August 31, 1985 (November 1983) 5. LEASE DESIGNATION AND BERIAL NO (Formerly 9-331) BUREAU OF LAND MANAGEMENT NM - 77018 G. IF INDIAN, ALLOTTER OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT..." for such proposals.) RECEIVED 7. UNIT AGRESHENT NAME WELL [] OTHER 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Pecos Valley "7" Collins & Ware, Inc. D. W.BLI. NO. 3. ADDRESS OF OPERATOR 303 W. Wall, Suite 2200 Midland, TX 79701 for and in accordance with any State requirements. See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT Rustler Bluff Atoka At surface 11. SEC., T., B., M., OR BLK. AND BURYET OR ARMA 534' FNL and 1414' FWL of Section 7 Sec.7, T-24-S, R-29-E 12. COUNTY OR PARISH 13. STATE 15 ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. Eddy MM 2976.7' GR Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT FRACTURE TREAT SHOOTING OR ACIDIZING ABANDON SHOOT OR ACIDIZE INTERMEDIATE (SQ. CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly State all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* An eight and one-half inch hole was drilled to 10,600' K.B. on November 28, 1991. 7" 29#/ft., P-110 LT&C and Buttress casing was run and set at 10,600' K.B. Cemented first stage with 650 sacks Halliburton Premium cement with 5# KCL/SK., 0.6% Halad 22A, and 0.5% CFR-3 (1.24 cu. ft.,/ SK. yield 15.6#/gallon). Plug down at 6:30 PM November 28, 1991. Cemented second stage with 260 sacks Halliburton Lite Premium cement. with 8# salt/SK, 1/4# flocele/SK. and 0.5% Halad 22A (2.1 cu. ft./ SK. yield, 12.4#/gallon). Tailed in with 760 sacks 50/50 poz. with 0.6% Halad 322 and 6# salt/SK.(1.35 cu. ft./ SK. yield, 14.2#/gallon). Plug down at 2:04 AM November 29, 1991. Waited on cement 26-3/4 hours. Tested BOP, manifold and safety valves to 10,000# psig. 18. I hereby certify that the forgeting is true and correct for Collins & Ware, Inc DATE 12/12/91 SIGNEL (This space for Federal or State office use) DATE .

TITLE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: