(Other)

IN OIL CONS. COM

Form approved.

Alpha Twenty-One Production Company Cities 3 F Discrete Section of Well (Report location clearly and in Accordance with any State requirements.* At surface Cities 3 F 9. Well NO. 3 10. FIELD AND POOL Washington 11. Sec., T., R., M., O	TEE OR TRIBE NAME	
OIL X WELL X WELL OTHER NAME OF OPERATOR Alpha Twenty-One Production Company Cities 3 F Address of Operator 2100 First National Bank Building, Midland, Texas 79701 Location of Well (Report location clearly and in accordance with any State requirements.* At surface Washington 11. Sec., T., R., M., O		
Alpha Twenty-One Production Company Cities 3 F Discrete Section of Well (Report location clearly and in Accordance with any State requirements.* At surface Cities 3 F 9. Well NO. 3 10. FIELD AND POOL Washington 11. Sec., T., R., M., O	NAME	
2100 First National Bank Building, Midland, Texas 79701 3. Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Washington 11. sec., T., R., M., O	S. FARM OR GEASE NAME	
2100 First National Bank Building, Midland, Texas 79701 3 Location of Well (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Washington 11. sec., T., R., M., O	ederal	
LIDEATION OF WELL (Report location clearly and in accordance with any State requirements.* Note also space 17 below.) At surface 10. FIELD AND POOL. Washington 11. SEC., T., R., M., O		
LIDEATION OF WELL (Report location clearly and in accordance with any State requirements.* Note also space 17 below.) At surface 10. FIELD AND POOL. Washington 11. SEC., T., R., M., O		
	Ranch-Delaware	
SURVEY OR AS		
2121' FNL and 1650' FWL Section 3,	T26S, R24E	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARI	SH 13. STATE	
3734 Ground Level Eddy	New Mexico	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF PULL OR ALTER CASING REPAIRING WELL PRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT SHOOTING OR ACIDIZING SITOOT OR ACIDIZE CHANGE PLANS (Other) REPAIR WELL

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

We Plugged and Abandoned this well using the following procedure:

Set a CIBP at 1300' and dumped 35' of cement on top.

Perforated at 675' and squeezed with 100 sacks of cement. Cement circulated.


Placed 15 sacks cement plug at the surface.

Erected monument at wellsite.

Work accomplished September 29, 1981.

(USGS Rep. Bert Jones was on location)

We will notify USGS when location is cleaned and ready for inspection.



ON A GAS U.S. GEOLOGICAL SURVEY

7 .		DSWELL, NEW MEXICO	
18. I hereby certify that the taregoing is true and correct SIGNED Tommy Phi pps	TITLE Executive Vice President	DATE October 19, 1981	
This space for Pederal or state affice use)	TITLE	DATE	
100 4 1982 FOR *Se JAMES A. SILLHAM 20 3 100 6 SHEERWING	e Instructions on Reverse Side		