## Bratcher, Mike, EMNRD

From:Jones, Kellie, EMNRDSent:Wednesday, October 07, 2015 8:59 AMTo:Everhart, HarleyCc:Patterson, Heather, EMNRD; Bratcher, Mike, EMNRDSubject:RE: Cedar Brakes Spiill / Unit 3685\_10.6.15

Harley,

This site is actually in District II and all actions regarding this site is handled by either Mike Bratcher or Heather Patterson at (575) 748-1283.

Thanks,

Kellie Jones Environmental Specialist, District 1 Oil Conservation Division, EMNRD 575-393-6161 ext. 111 575-370-3180 (emergency-cell) E-Mail: <u>kellie.jones@state.nm.us</u>

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Everhart, Harley [mailto:heverhart@akaenergy.com]
Sent: Tuesday, October 06, 2015 2:10 PM
To: Jones, Kellie, EMNRD
Subject: FW: Cedar Brakes Spiill / Unit 3685\_10.6.15
Importance: High

## Hello Kellie

			Frontier Field			
3685	6/23/2015	Ini c-141	Services	Maljamar Gas plant	18S 31E 14	

Just touching base with you to see if you have any reservations about Frontier Field Services backfilling Cedar Break with clean soil?

Harley Everhart

From: Pair, Randal [mailto:rpair@blm.gov]
Sent: Friday, October 02, 2015 2:32 PM
To: Everhart, Harley <<u>heverhart@akaenergy.com</u>>
Cc: Jones, Kellie, EMNRD <<u>Kellie.Jones@state.nm.us</u>>; Busch, Greg <<u>gbusch@akaenergy.com</u>>; Calderon, Joe

<<u>icalderon@akaenergy.com</u>> **Subject:** Re: Initial C-141\_Cedar Brakes Spill\_10.2.15

Fri 10-2-2015

Harley - based on these lab results, I give BLM's approval to backfill the emediaiton site. please use clean - not remediated - fill.

Randal "Randy" Pair Envir. Protection Specialist - Realty Compliance office: 575.234.6240 cell: 575.361.0062 email: <u>rpair@blm.gov</u>

On Fri, Oct 2, 2015 at 12:40 PM, Everhart, Harley <<u>heverhart@akaenergy.com</u>> wrote:

Kellie Jones, NMOCD

Randal Pair, BLM

RE: Cedar Brake Spill, Unit Letter 3685

Frontier Field Services is respectfully requesting to move forward with the completion of this remediation project. Attached to this email you will find;

1) PDF/DWG sample location.

2) Analytical results,

If you have any additional questions, please feel free to contact me at any time.

Respectfully,

Harley Everhart

EH&S Compliance

(575) 677-5140 - Direct

(575) 513-4922 - Cell

(575) 676-2401 - Fax

heverhart@akaenergy.com



## CONFIDENTIALITY NOTICE:

This email, including attachments, may include confidential and/or proprietary information, and may be used only by the person or entity to which it is addressed. Please do not read, copy or disseminate this communication unless you are the intended addressee. If you have received this communication in error, please permanently delete and call (575) 677-5140 immediately and ask to speak to the sender of this communication. Also, please notify immediately via email that you have received this message in error.

From: Jones, Kellie, EMNRD [mailto:Kellie.Jones@state.nm.us]
Sent: Tuesday, June 23, 2015 9:42 AM
To: Everhart, Harley <<u>heverhart@akaenergy.com</u>>; rpair@blm.gov
Cc: Busch, Greg <<u>gbusch@akaenergy.com</u>>; Prentiss, John <<u>jprentiss@akaenergy.com</u>>; Quiroz, Rudy
<<u>rquiroz@akaenergy.com</u>>
Subject: RE: Initial C-141\_Cedar Brakes Spill\_6.23.2015

Harley,

Please see below for your recent submittal.

í							
				Frontier			
				Field			
	3685	6/23/2015	Ini c-141	Services	Maljamar Gas plant	18S 31E 14	

Please call if you have any questions.

Have a great day!

Kellie Jones

Environmental Specialist, District 1

Oil Conservation Division, EMNRD

(575) 393-6161 ext. 111

575-370-3180 (emergency-cell)

E-Mail: kellie.jones@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

Please note:

-The OCD is no longer granting "risk-based," or standard closure of events/RPs with remediation deferred to site abandonment/sale/closure. The RP will remain open until such time as historic contamination is addressed.

-Photographic documentation is stipulated for all events involving liquids.

If you have any questions or concerns, and for notification, please contact me.

From: Everhart, Harley [mailto:heverhart@akaenergy.com]
Sent: Tuesday, June 23, 2015 8:42 AM
To: Jones, Kellie, EMNRD; rpair@blm.gov
Cc: Busch, Greg; Prentiss, John; Quiroz, Rudy
Subject: Initial C-141\_Cedar Brakes Spill\_6.23.2015

NMOCD/BLM;

Attached is the initial C-141 for the Cedar Brakes Spill located at Latitude <u>32° 75' 43.16" N</u> Longitude <u>103° 84' 19.31" W</u>.

The cause and conditions of the spill was identified and alleviated. Excavation will commence until TPH, BTEX, and Benzene are below the levels outlined in "NMOCD Guidelines for Remediation of Leaks, Spills, and Releases". Impacted soils will be transported to an OCD approved facility for disposal and the area will be backfilled with clean soil.

Should you have any comments or concerns, please do not hesitate to contact me anytime.

Thank you for your leadership on this matter.

Respectfully,

Harley Everhart

EH&S Compliance

(575) 677-5140 - Direct

(575) 513-4922 - Cell

(575) 676-2401 - Fax

heverhart@akaenergy.com



## CONFIDENTIALITY NOTICE:

This email, including attachments, may include confidential and/or proprietary information, and may be used only by the person or entity to which it is addressed. Please do not read, copy or disseminate this communication unless you are the intended addressee. If you have received this communication in error, please permanently delete and call (575) 677-5140 immediately and ask to speak to the sender of this communication. Also, please notify immediately via email that you have received this message in error.