From:	Groves, Amber	
To:	tpassmore@mar-win.com	
Cc:	bcccorp@aol.com; Yu, Olivia, EMNRD	
Subject:	RE: Revegetation Plan 1R-4526	
Date:	Monday, April 17, 2017 9:20:04 AM	
Attachments:	image001.png	
	image003.png	

Good Morning, Todd,

Your revegetation plan is approved.

Thank you,

#### **Amber Groves**

.....

Remediation Specialist Field Operations Division (575)392-3697 (575)263-3209 cell New Mexico State Land Office 2827 N. Dal Paso Suite 117 Hobbs, NM 88260

**CONFIDENTIALITY NOTICE** - This e-mail transmission, including all documents, files, or previous e-mail messages attached hereto, may contain confidential and/or legally privileged information. If you are not the intended recipient, or a person responsible for delivering it to the intended recipient, you are hereby notified that you must not read this transmission and that any disclosure, copying, printing, distribution, or use of any of the information contained in and/or attached to this transmission is STRICTLY PROHIBITED. If you have received this transmission in error, please immediately notify the sender and delete the original transmission and its attachments without reading or saving in any manner. Thank you.

From: Todd Passmore [mailto:tpassmore@mar-win.com]
Sent: Monday, April 17, 2017 7:49 AM
To: Groves, Amber <agroves@slo.state.nm.us>
Cc: bcccorp@aol.com
Subject: FW: Revegetation Plan 1R-4526

Good morning Amber,

Do you approve this re-seeding plan? Just confirming that the re-seed concentration per acre is approved

Thanks,

Todd Passmore Marshall & Winston Inc.

From: Todd Passmore [mailto:tpassmore@mar-win.com]
Sent: Friday, April 7, 2017 8:32 AM
To: 'Groves, Amber' <a groves@slo.state.nm.us</li>
; 'Yu, Olivia, EMNRD' <<u>Olivia.Yu@state.nm.us</u>
Cc: tflemmons@mar-win.com
Subject: Revegetation Plan 1R-4526

Good morning.

Please see attached official revegetation plan for the Loco Dinero spill 1R-4526.

Please let me know if you have any questions or concerns.

Thank you,

Todd Passmore Operations Manager Marshall & Winston Inc. Office: 432-684-6373

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <u>http://www.symanteccloud.com</u>

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com 3302 122nd Street Lubbock, Texas 79423 Mailing Address: P.O. Box 53427 Lubbock, Texas 79453 Phone: 806-771-8033 Fax: 806-687-6926 www.bcccorp.com





Marshall & Winston, Inc. Loco Dinero 36 State 2H Produced Water Spill (Some Oil) Affected Area – 92,310 sq. ft. / 2.12 acres GPS Coordinates: N32.444077 W103.465883

## OCD Case Number 1R-4526

3302 122nd Street Lubbock, Texas 79423 Mailing Address: P.O. Box 53427 Lubbock, Texas 79453 Phone: 806-771-8033 Fax: 806-687-6926 www.bcccorp.com





#### Revegetation and Noxious Weed Management Plan for Marshall & Winston, Inc. Loco Dinero 36 State 2H Release OCD Case Number 1R-4526

April 6, 2017

Once all of the excavated areas have been backfilled, contoured, and the remediation requirements have been met, Marshall & Winston, Inc. proposes the following revegetation and noxious weed management plan for OCD Case Number 1R-4526, the Loco Dinero 36 State 2H release:

### Seed Mix – Certified Weed Free Seed:

Blue Grama	30.00%	1.5 PLS lbs./acre
Sideoats Grama	27.00%	4.5 PLS lbs./acre
WW Spar Bluestem	8.00%	1.8 PLS lbs./acre
Blackwell Switchgrass	8.00%	3.5 PLS lbs./acre
Sel 75 Kleingrass	8.00%	1.5 PLS lbs./acre
Sand Dropseed	6.00%	1.0 PLS lbs./acre
Texoka Buffalograss	6.00%	8.0 PLS lbs./acre
Little Bluestem	5.00%	3.4 PLS lbs./acre
VNS Tall Fescue	2.00%	4.0 PLS lbs./acre
	100.00%	

The seeding would be done by mechanical broadcast at the rate of 20 lbs./acre as soon as remediation requirements have been met and the plan has been approved by the NMSLO staff (approximate late April timing). After reseeding of the site is complete, continuous monitoring will take place to determine if any more seed needs to be applied, or if there has been any noxious weed invasions. If any noxious weeds were to emerge, chemical treatment would be used to eradicate the problem once the weed species has been identified. Continuous monitoring and any needed follow-up treatments would be maintained until the revegetation of this site is determined to be complete.

Marshall & Winston, Inc. Loco Dinero 36 State 2H Produced Water Spill (Some Oil) Affected Area - 92,310 sq. ft. / 2.12 acres GPS Coordinates: N32.444077 W103.465883

00



© 2016 Google

8

• •

050

....

00

# Google Earth

Imagery Date: 2/1/2017 lat 32.442790° lon -103.462943° elev 3720 ft eye alt 4933 ft

8 6 8 8

01

86

8