Subm Office	it 3 Copies To Appropriate District	State of New Mexico		Form C-103			
<u>Distri</u> 1625	ct I N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		ral Resources	Revised June 10, 2003 WELL API NO.		
Distri	CIL CONCEDIATION DIVIGION			DIVICION	30-025-36504		
1301 Distri	it W. Grand Ave., Artesia, NM 88210  OIL CONSERVATION DIVISION  1220 South St. Francis Dr.				5. Indicate Type of Lease		
	O Rio Brazos Rd Aztec NM 87410						
1220	District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505  Santa Fe, NM 87505				6. State Oil & G	as Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease Name of	or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				G1 11 25 G1 1		
PROF	ROPOSALS.)				Shelley 35 State  8. Well Number		
	ype of Well:	0.1			008		
		Other					
2. Name of Operator  Tom Brown Inc.					9. OGRID Numl	oer	
Tom Brown, Inc.  3. Address of Operator					023230	YYY'1 1	
3. Address of Operator P O Box 2608, Midland, TX 79702					10. Pool name or Wildcat Skaggs; Drinkard, Northwest (96768)		
4. Well Location							
	Unit Letter <u>C</u> : 8	feet from the	North	line and180	on feet from	m the West line	
	Section 35	Township	19S	Range 37E	NMPM	County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:							
PER	FORM REMEDIAL WORK		νП				
	DRARILY ABANDON						
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB				1D 🗀			
OTHER: OTHER: Completion							
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date							
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion							
or recompletion.							
	1/22/04 MIRU Completion Rig. PBTD 7148' 1/23/04 Perf Drinkard 7006-7016, 4 SPF. RIH w/ tbg & pkr				30.32		
1/24/04 Pkr set @ 7035. Spot 200 gals 15% HCL NEFE acid. Acidize Perfs 7006-7016 w/ 3000 gals 15% HCL NEFE acid. Swab							
	well						
	1/28/04 POOH w/ tbg & pkr. ND BOP						
	1/29/04 RIH w/ 5-1/2" CIBP & set @ 6970' w/ 20' cmt on top. New PBTD 6950'. Perf Drinkard 6800-6810; 3 SPF 2/03/04 Re-perf 6800-6810 w/ 3 SPF. RIH w/ tbg & pkr. Pkr set @ 6693. Acidize perf 6800-6810 w/ 3000 gals 15% HCENEFE acid						
Swab well							
2/04/04 Released pkr. POOH w/ tbg & pkr. ND BOP. Frac perfs 6800-6810 w/ 36,700 gals Viking-2500 & 8300 lb. of 20/40 wh					28300 lb. of $20/40$ white		
<b>2</b> (2 <b>5</b> (4	sand	D1			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	, 15 <sup>7</sup> /	
2/05/04 NU BOP, RIH w/ tbg & pkr. Pkr set @ 6693. ND BOP 2/06/04 NU BOP, release pkr & pooh. POOH w/ tbg. Perf 6762-6772, 6781-6791 6842-6848 w/ 3 SPF. RIH w/ tbg & pkr. Pkr							
2/00/0	104 NU BOP, release pkr & poon. POOH w/ tog. Peri 6/62-6/72, 6/81-6/91 6842-6848 w/ 3 SPF. KIH w/-tog & pkr. Pkr set @ 6673. ND BOP. NU 5K tree						
2/09/0			Pkr set @ 6693. ND BOP POOH w/ tbg. Perf 6762-6772, 6781-6791 6842-6848 w/ 3 SPF. RIH w/ tbg & pkr. Pkr set @ 20% HCL NEFE acid. kr. POOH w/ tbg & pkr. RIH w/ rod & tbg.				
	/10/04 ND tree. NU BOP, released pkr. POOH w/ tbg & pkr. RIH w/ rod & tbg.						
2/11/0	Set pumping unit and turn	well to production.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE Jan Grand a TITLE Operations Asst / Tech DATE 3/11/04							
Type or print name Diane Kuykendall V E-mail address: dkuykendall@tombrown.com Telephone No. 432-688-9773							
	space for State use)		and non			7.1.0. 100 000-7770	
APD 0.1 av							
APPPROVED BY TITLE PETROLEUM ENGINEED DATER U 1 2004							

APPPROVED BY Conditions of approval, if any: