

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.
30-025-24944

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
013645

7. Lease Name or Unit Agreement Name
Aztec State

8. Well No. 14

9. Pool name or Wildcat
Corbin Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Lynx Petroleum Consultants, Inc

3. Address of Operator
3325 Enterprise Drive, Hobbs, NM 88241

4. Well Location
Unit Letter C : 660 Feet From The North Line and 2030 Feet From The West Line

Section 36 Township 17-S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3978' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 8350'. Cap w/ 15 sx. cement.
2. Pull casing from 6000'.
3. Spot a 50 sx. plug in and out of casing stub. WOC and tag.
4. Spot a 50 sx. plug from 4300'-4100'. WOC and tag.
5. Spot a 40 sx. plug from 3560'-3460'.
6. Spot a 75 sx. plug from 3025'-2925'. WOC and Tag
7. Spot a 75 sx. plug from 2360'-2460'. WOC and Tag.
8. Spot a 75 sx. plug from 1370'-1320'. WOC and Tag.
9. Spot a 100 sx. plug from 390'-250'. WOC and Tag.
10. Spot a 10 sx. surface plug and dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

Perforations from 8406'-8469'. 12-1/2" @ 340', 8-5/8" @ 2975', 5-1/2" @ 8703'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. Boatright TITLE Agent

DATE 3/28/04

TYPE OR PRINT NAME H. Boatright

TELEPHONE NO. 432/570-5382

(This space for State Use)

APPROVED BY Larry W. Wink
COMPETENT OF APPROVAL, NAME:

OIL FIELD REPRESENTATIVE II/STAFF MANAGER APR 02 2004