

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised June 10, 2003

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p> <p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/></p> <p>2. Name of Operator HANSON OPERATING COMPANY, INC.</p> <p>3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88202-1515</p> <p>4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line Section <u>19</u> Township <u>22 South</u> Range <u>38 East</u> NMPM <u>Lea County</u></p> <p>11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3344.6' GR</p>		<p>WELL API NO. 30-025-31745</p> <p>5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/></p> <p>6. State Oil & Gas Lease No.</p> <p>7. Lease Name or Unit Agreement Name Max Gutman</p> <p>8. Well Number #11</p> <p>9. OGRID Number 009974</p> <p>10. Pool name or Wildcat South Brunson Drinkard Abo</p>
---	--	--

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: Recompletion ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/19/1996: MIRU.
10/21/1996: TOH with rods, pump and tubing. TIH with RBP and set at 7235'.
10/22/1996: Perforate 73 holes at 6572'-7197'.
10/23/1996: Acidize perforations at 6988'-7197' with 5,000 gallons 20% acid.
10/24/1996: Acidize perforations at 6572'-6919' with 5336 gallons 20% acid.
10/25/1996: Frac perforations at 6572'-6919' with 156,300# 16/30 sand. Test and evaluate.
10/29/1996: TIH with RBP and set at 6095'.
11/4/1996: Latch on to RBP at 6095'. TOH.
11/5/1996: TIH with production string.
11/6/1996: TIH with pump and rods. Place well on production.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carol J. Garcia TITLE Production Analyst DATE 04/02/2004

Type or print name Carol J. Garcia E-mail address: hanson@dfn.com Telephone No. 505-622-7330

(This space for State use)

APPROVED BY Chris Williams TOUCH DISTRICT SUPERVISOR/GENERAL MANAGER APR 05 2004

Conditions of approval, if any: