Submit 3 Copies To Appropriate District Office District I	State of New Mexico Encrgy, Minerals and Natural Resources				Form C-103 Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.			
District II 1301 W. Grund Ave., Artesia, NM 88210	1 Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-025-31745		
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			STATE FEE S 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505				o. State Off &	Gas Lease No).	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH							
PROPOSALS.)				Max Gutman			
I. Type of Well: Oil Well ☑ Gas Well ☐ Other				8. Well Number			
				#11			
2. Name of Operator HANSON OPERATING COMPANY, INC.				9. OGRID Number			
3. Address of Operator				009974			
P. O. Box 1515, Roswell, New Mexico 88202-1515				10. Pool name or Wildcat South Brunson Drinkard Abo			
4. Well Location				South Brunson Dirikaru Abo			
						İ	
Unit Letter C :	990 feet from the	Nort	<u>h</u> line and	1650 feet 1	from the <u>V</u>	Vest line	
Section 19	Township 2	22 South	Range 38 Ea	act NN	ou las		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				351	IPM Lea	County	
	3344.6' GR		,			: 2 : 2	
12. Check Ap	propriate Box to Inc	dicate N	ature of Notice, 1	Report or Othe	r Data		
NOTICE OF INTENTION TO: SUBS				SEQUENT R		F:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING	CASING 🔲	
	CHANGE PLANS		COMMENCE DRIL	.LING OPNS.	PLUG AND		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN	D 🗆	ABANDON	IVIENI	
OTHER:		_					
	ted operations (Clause		OTHER: Rec	ompletion			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 05/12/1997: MIRU. TOH with rods. 05/14/1997: TOH with rods, pump and tubing. 05/16/1997: Latch on to and release RBP at 7235'. 05/17/1997: TOH with RBP. 05/19/1997: Clean hole to 7427'. TIH with production string. TIH with pump and rods. Place well on production.							
					20222	_	
05/12/1997: MIRU. TOH with	rode			(6	89101115	737	
05/14/1997: TOH with rods, pump and tubing.							
05/16/1997: Latch on to and release RBP at 7235'.							
05/17/1997: TOH with RBP.							
05/19/1997: Clean hole to 7427'. TIH with production string.							
05/20/1997: TIH with pump and rods. Place well on production.							
				130		11.	
				100	5 K2020747	E 10 10	
					00000		
hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE Carol	Larcia 1	TTLE	Production A	inalvet	DATE 04	4/02/2004	
Type or print name Carol J. G		address:	hanson@dfn.co				
(This space for State use)							
APPPROVED BY Chris William ORIGINAL SIGNED BY APR 0 5 2004							
APPPROVED BY Chus William CHRISIWHLIAMS Conditions of approval, if any: OC DISTRICT SUPERVISOR OF MERAL MANAGER DATE							
OC DISTRICT SOCERAIS ACT AND A							