Submits Copies To Appropriate District State of New Mexico Office Financy Minerals and Natural Passaurces	Form C-103
District I 1625 N. French Dr., Hobbs, NM 87240	Revised March 25, 1999 WELL API NO. 20, 035, 11000
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION	30-025-11000 5. Indicate Type of Lease
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE FEE X
District IV 2040 South Pacheco, Santa Fe, NM 87505	6. State Oil & Gas Lease No. 8910138170 -
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Myers Langlie Mattix Unit
1. Type of Well: Oil Well X Gas Well Other	Type of Language Maconix on to
2. Name of Operator	8. Well No.
OXY USA WTP Limited Partnership 192463	149
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250 4. Well Location	9. Pool name or Wildcat Langlie Mattix 7Rvr Qn-GB
Unit Letter H: 1980 feet from the north line and	660 feet from the east line
Section 4 Township 24S Range 37E	NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, et 3293'	
11. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	ING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER: MIT - TA	Status
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. OXY USA WTP 1P requests to temporarily abandon this well for possible future use	
OXY USA WTP LP requests to temporarily abandon this well for possible future use.	
TD-3701' PBTD-3400' OH-3459-3656' CIBP-3400' 1. 3/16/04-POOH w/ rods, pump & tbg, RIH and set CIBP @ 3400', CHC w/ pkr fluid, NDBOR, NDWH.	
1. 3/16/04-POOH w/ rods, pump & tbg, RIH and set CIBP @ 3400', CHC w/ pkr fluid, NDBOR, NDWH.	
2. Notify NMOCD of casing integrity test 24hrs in advance.	
3. RU pump truck 3/31/04, circulate well with treated water, pressure test casing to 500# for 30 min. This Approval of Temporary 3/31/09 Abandonment Expires	
hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURETITLE Sr. Regulatory	Analyst DATE 465 OF

Telephone No.

OC FIELD REPRESENTATIVE II/STAFF MANAGEATE

432-685-5717

Type or print name David Stewart

(This space for State use)

APPROVED BY Lar Conditions of approval, if any:

