RECEIVED

Oil Cons. N.M. DIV-Dist. 2 1301 W. Grand Avenue

APR 0 8 2004

GWW

FORM A	PROVED
OMB No.	1004-0135
Expires Janu	ary 31, 2004

Sundry Notices and Reports on Wells Do not use this form 3160-3 (APD) for such proposals. UNITED STATES Artesia, NM 8821 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004 5. Lease Serial No. NMO 47 4 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well						
Oil Well Gas Well Other				8. Well Name and No. Federal "B" No. 2		
2. Name of Operator H. L. Brown Operating, L.L.C. OGRID# 213179			9. API W			
H.L. Brown Operating, L.L.C. OGRID# 213179 3a. Address 3b. Phone No. (include area code)		30-041-20904				
P.O. Box 2237, Midland, TX 79702 (432) 688-3726		10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description	1)			t Wolfcamp (Gas)	
1310 ft. FNL & 133	30 ft. FEL			11. County	or Parish, State	
Sec. 4, T-8-S, R-3	37-E			Roosevelt, NM		
12. CHECK AP	PROPRIATE BOX(ES) TO	O INDICATE NATO	JRE OF NOTICE, I	REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION			YPE OF ACTION			
	Acidize	Deepen Deepen	Production (Sta	rt/Resume)	☐ Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	,	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
- Subsequent Report	Change Plans	Plug and Abandon	Temporarily A	bandon	Initial Completion	
☐ Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
13. Describe Proposed or Complete	d Operation			***		
down to 8002 02/11/04 PU 4-3/4" bit a formation. Ci 02/16/04 Opened well packer and to 02/19/04 Ran bottom-h 02/26/04 Retrieved bottom-h 03/05/04 MIRU Gray V 03/12/04 RU BJ Servicing gallons cross	". Circ. hole clean and and drill collars and RIH reulated hole clean and and bled down. POOH abing. Set packer at 79 nole pressure bombs to mbs and ran static grad Vireline. Perforated the ces. Acidized perfs and	POOH. RU Gray I. Drilled 4' ceme I POOH with 64 jt with tubing and L 05' with the end o the SN. Finished dients. Put well or Wolfcamp in two open hole with 5 gallons gelled acid	Wireline and logant and float shoes tubing. SI & SE D drill collars. Pf tubing at 7941'. hooking up produsales at the rate σ runs from 7990' σ	ged GR/ C at 8006'. O due to we U and RIH ND BOP duction equ to 155 mi to 8005 a 5% NEFE	and flanged up wellhead hipment 78 2-%" Arrowset with 5-1/2" x 2-%" Arrowset and flanged up wellhead hipment 78 25 25 25 25 25 25 25 25 25 25 25 25 25	
14. I hereby certify that the foregoi Name (Printed/Typed)		TOTAL .	D 5 1 T-			
Robert T. McNaugh	ton	Title	Title Petroleum Engineer			
Signature	· · · · · · · · · · · · · · · · · · ·	Date	Date 3-26-04			
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE US	SE : 20 1		
	al or equitable title to those right conduct operations thereon.	nts in the subject lease	Title Office on knowingly and willful signification.	lly to make to a	Pate ED FOR RECORD	
(Instructions on reverse)					RMANDO A. LOPEZ FROLEUM ENGINEER	
(~ ∨∨ ∨ \				I h i	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	